







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8554</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9833857590																													
<b>Technician Name :</b>	Ishwar Meena		<b>Technician Mobile :</b>	9165341500																										
<b>Ticket Type :</b>	AMC visiting	<b>Date &amp; Time :</b>	12-06-2023 12:00:29																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																										
<b>Product Name :</b>	Ppm																													
<b>Complain :</b>	CCTV PPM Need to do																													
<b>Technician Comment :</b>	(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-06-2023 04:02:54</td><td>Ishwar Meena</td><td>Completed</td><td>(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.</td><td></td></tr><tr><td>20-06-2023 10:22:53</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>12-06-2023 05:24:02</td><td>Ishwar Meena</td><td>Work Pending</td><td>All cameras lences clean and 3/4 cameras angel settings done and one camera film remooved and bwing near dvr one analog camera faulty so remooved and collect And one shop side ip camera faulty cable ok repunching camera end ip 66 box also need old box break ppm done .</td><td></td></tr><tr><td>12-06-2023 12:00:42</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-06-2023 04:02:54	Ishwar Meena	Completed	(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.		20-06-2023 10:22:53	Ishwar Meena	New		-	12-06-2023 05:24:02	Ishwar Meena	Work Pending	All cameras lences clean and 3/4 cameras angel settings done and one camera film remooved and bwing near dvr one analog camera faulty so remooved and collect And one shop side ip camera faulty cable ok repunching camera end ip 66 box also need old box break ppm done .		12-06-2023 12:00:42	Ishwar Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																										
20-06-2023 04:02:54	Ishwar Meena	Completed	(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.																											
20-06-2023 10:22:53	Ishwar Meena	New		-																										
12-06-2023 05:24:02	Ishwar Meena	Work Pending	All cameras lences clean and 3/4 cameras angel settings done and one camera film remooved and bwing near dvr one analog camera faulty so remooved and collect And one shop side ip camera faulty cable ok repunching camera end ip 66 box also need old box break ppm done .																											
12-06-2023 12:00:42	Ishwar Meena	New		-																										

Previous Complain History :			
	Date Time	Technician Name	Remark
	07-06-2023 10:38:21	Kalpesh SubhashGurav	New Crystal Power supply Installed OK A/1203 - New Telephone Required B1301 - OK Main Gate Security Required Extra Ringer
	02-06-2023 12:13:08	Munna Gupta	intercom system mein kisi bhi extension mein phone mein ring nahin baj raha hai. intercom system mein power supply ka problem hai.