Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE9997 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9867709139 **No. : Technician Name** Dilshad Khan **Technician Mobile** 9324177692 Complain 06-11-2023 11:09:46 **Ticket Type : Date & Time :** Vendor Details : **Rahul International** Customer's 9867709139 Company Name : Kalpesh Sir Name/Client Name School CBSE Mobile : Nalasopara West Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain** : main building Ground & 1st Floor DVR is getting reboot frequently. Due to that cameras are not working. 2 camera fabulous issu Resolved and solve and 1 camera no video issu Resolved and solve **Technician Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 2 camera fabulous issu Resolved and solve and 1 camera no video issu Resolved and solve **Status History : Date Time Technician Name** Status Remark Sign 06-11-2023 03:29:43 DilshadKhan Completed 2 camera fabulous issu Resolved and solve and 1 camera no video issu Resolved and solve 06-11-2023 12:48:04 DilshadKhan New **Previous Date Time Technician Name** Remark **Complain History** 07-12-2023 11:38:19 Ravi Rajbhar 5 th floor passages new bullet camera install and ok working done faulty against and ground floor dvr recoding check properly going on in dvr recoding and 1th floor check also 10-10-2023 10:49:41 Sonu Kumar Cctv ppm done some cameras angle set