







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4380																																																		
Priority :	Low																																																	
Created By :	Admin - Apurva Vajaria																																																	
Complaint Mob. No. :	9220755431																																																	
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																																														
Ticket Type :	Complain	Date & Time :	14-12-2021 11:25:29																																															
Vendor Details :																																																		
Company Name/Client Name :	Dahisar Kaka	Customer's Mobile :	9220755431	Name :	Karan Soni																																													
Address :																																																		
Mumbai , , , , Maharashtra																																																		
AMC Details :																																																		
Expiry Date :	01-01-1970 05:30:00		Type :																																															
Product Name :	EPABX																																																	
Complain :	EPABX Shifting																																																	
Technician Comment :	one drilling for home cable . one old camera fixed again 4*4box with angle setting also done. intercom work pending. two new line requirement. and 20mtrs cabling also needed for intercom																																																	
Complain Operator :	Desktop - Apurva Vajaria																																																	
Remark :	one drilling for home cable . one old camera fixed again 4*4box with angle setting also done. intercom work pending. two new line requirement. and 20mtrs cabling also needed for intercom																																																	
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-12-2021 05:59:00</td><td>Neeraj Chauhan</td><td>Work Pending</td><td>one drilling for home cable . one old camera fixed again 4*4box with angle setting also done. intercom work pending. two new line requirement. and 20mtrs cabling also needed for intercom</td><td></td></tr><tr><td>25-12-2021 10:27:00</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>23-12-2021 07:08:52</td><td>Neeraj Chauhan</td><td>Work Pending</td><td>apbx system port not available.</td><td></td></tr><tr><td>23-12-2021 03:33:52</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>17-12-2021 10:26:50</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>15-12-2021 10:31:25</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>14-12-2021 11:26:03</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>14-12-2021 11:25:29</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-12-2021 05:59:00	Neeraj Chauhan	Work Pending	one drilling for home cable . one old camera fixed again 4*4box with angle setting also done. intercom work pending. two new line requirement. and 20mtrs cabling also needed for intercom		25-12-2021 10:27:00	Neeraj Chauhan	New		-	23-12-2021 07:08:52	Neeraj Chauhan	Work Pending	apbx system port not available.		23-12-2021 03:33:52	Neeraj Chauhan	New		-	17-12-2021 10:26:50	Neeraj Chauhan	New		-	15-12-2021 10:31:25	Neeraj Chauhan	New		-	14-12-2021 11:26:03	Neeraj Chauhan	New		-	14-12-2021 11:25:29	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																																														
25-12-2021 05:59:00	Neeraj Chauhan	Work Pending	one drilling for home cable . one old camera fixed again 4*4box with angle setting also done. intercom work pending. two new line requirement. and 20mtrs cabling also needed for intercom																																															
25-12-2021 10:27:00	Neeraj Chauhan	New		-																																														
23-12-2021 07:08:52	Neeraj Chauhan	Work Pending	apbx system port not available.																																															
23-12-2021 03:33:52	Neeraj Chauhan	New		-																																														
17-12-2021 10:26:50	Neeraj Chauhan	New		-																																														
15-12-2021 10:31:25	Neeraj Chauhan	New		-																																														
14-12-2021 11:26:03	Neeraj Chauhan	New		-																																														
14-12-2021 11:25:29	Neeraj Chauhan	New		-																																														

Previous Complain History :	Date Time	Technician Name	Remark
	15-04-2023 10:52:41	SantoshPathak	Kalpesh visited - Extension number 235 - ok
	09-03-2023 11:25:07	Atique Salmani	One smmps cahaned and working ok and which one cameras fractuating some light reflection and some i.r burn so cameras need to changed . also check restart dvr working ok.