Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE7636					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob.	9220755431					
Technician Name :	Atique Salmani		Techr	nician Mobile :	8080922984	
Ticket Type :	Complain	Date & Time:	15-02	5-02-2023 12:12:25		
Vendor Details :						
Company Name/Client Name :	Dahisar Kaka	Customer's Mob	ile : 92207	755431	Name :	Karan Soni
Address:						
Mumbai , , , , Ma	harashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:	0 05:30:00				
Product Name:	CCTV					
Complain:	2nd DVR off issue and 1-2 camera fluctuation issue also 2 cameras night vision not getting on after shifting					
Technician Comment :	2ndvdvr 4pin power cable changed working ok 1camera need to changed and 1camera is also need to changed becz ir issue .2nd dvr under observation.					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	2ndvdvr 4pin power cable changed working ok 1camera need to changed and 1camera is also need to changed becz ir issue .2nd dvr under observation.					
Status History :	Date Time	Technician Name	Status	Rei	nark	Sign
	15-02-2023 01:56:26	Atique Salmani	Completed	2ndvdvr 4pin power cable changed working ok 1camera need to changed and 1camera is also need to changed becz ir issue .2nd dvr under observation.		Nasin
	15-02-2023	Atique Salmani	Completed	leted 2ndvdvr 4pin power cable changed working ok 1camera need to changed and 1camera is also need to changed becz ir issue .2nd dvr under observation.		1 , 1/1
	01:56:26			to changed becz i	r issue .2nd dvr	Nami
	15-02-2023 12:12:36	Atique Salmani	New	to changed becz i	r issue .2nd dvr	Naw!
Previous	15-02-2023	Atique Salmani Technician Nar		to changed becz i under observation	r issue .2nd dvr	Nami
Previous Complain History :	15-02-2023 12:12:36	Technician Nar	Dilshad vafter cha	to changed becz i under observation	r issue .2nd dvr n. emark 3 - 4 camera line iss	ue resolved