Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: valiabnsecure@yand									
Service Status Deta	ails: VE12380								
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	9920898984								
Technician Name	Atique Salmani		Technici	an Mobile 8080922984					
Ticket Type :	Complain	Date & Time :	08-08-2024 04:18:36						
Vendor Details :			•						
Company Name/Client Name :	Velji P. And Sons	Customer's Mobile :	9920898	984	Name :	Kaushik Sir			
Address:	_								
Mumbai , , , , Mah	arashtra								
AMC Details:									
Expiry Date :	15-08-2020 12:00:00		Type:	Comprehensive		е			
Product Name :	CCTV								
Complain:	Site : Cargo - DVR Adapter to be installed and online to be done								
Technician Comment :	Dvr adapter installation done working ok with 4caera recording and dvr to router cable cable also need to changed and dvr is too old so need also static IP for online mobile view.								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	Dvr adapter installation done working ok with 4caera recording and dvr to router cable cable also need to changed and dvr is too old so need also static IP for online mobile view.								
Status History :	Date Time	Technician Name	Status	Remark Dvr adapter installation done working ok with 4caera recording and dvr to router cable cable also need to changed and dvr is too old so need also static IP for online mobile view.		Sign			
	09-08-2024 04:23:55	Atique Salmani	Completed			e)			
	09-08-2024 10:10:24	Atique Salmani	New			-			
Previous Complain	Date Time	Technician Name	Remark						
Complain History :	12-12-2024 10:40:12	2 Sonu Kumar	Cctv acces	Cctv access ppm Dane all working ok all camera lens clean					
	27-09-2024 10:48:10	6 MayurYadav	Main door	released by disc	connect main door l	Main door released by disconnect main door lock connector from device Note- main door device bottom screw missing			