## Vallabh Enterprises

 $\label{eq:conditional} \textbf{Regd. Office}: 401, shanti kutir, shivaji road, near thakur international school, kandivali (west) mumbai - 400067 \\ \text{Support}: | \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in}$ 

E : vallabhsecure@yal	etails : VE4210						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	8097384039						
Technician Name :	Siddhesh Chavan		Technicia :	Technician Mobile :		8080922985	
Ticket Type:	Complain	12-11-202	12-11-2021 10:40:51				
Vendor Details :	-						
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - College	Customer's Mobi	le 80973840	39	Name :	Kedar Sir	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	31-05-2021 12:00:00		Type:	Type:		Comprehensive	
<b>Product Name:</b>	CCTV						
Complain:	seminar room cameras issue and principal meeting room cameras issue						
Technician Comment :	install new camera replacement against faulty camera and 2 nd floor passage camera no video issue resolved and camera under observation						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	install new camera replacement against faulty camera and 2 nd floor passage camera no video issue resolved and camera under observation						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	20-11-2021 11:49:04	Siddhesh Chavan	Completed	install new camera replacement against faulty camera and 2 nd floor passage camera no video issue resolved and camera under observation		Je	
	20-11-2021 10:31:01	Siddhesh Chavan	New			-	
	12-11-2021 01:45:05	Siddhesh Chavan	Work Pending	resolved an	om camera issue d seminar room e to office for	The	
	12-11-2021 10:41:16	Siddhesh Chavan	New			-	
	12-11-2021 10:40:52	Siddhesh Chavan	New			-	

<b>Previous</b>
Complain
<b>History</b> :

Date Time	Technician Name	Remark
14-02-2022 10:54:10	Siddhesh Chavan	ppm done and biomatric machines working ok one camera no video issue resolved
12-02-2022 09:59:24	Siddhesh Chavan	one out side camera install and one new 4by 4 box install and working ok