Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: vallabhsecure@yahoo.co.in							
Service Status De	tails: VE5430						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8097384039						
Technician Name :	Atique Salmani		Technici	an Mobile 8080922984			
Ticket Type :	Complain	Date & Time :	11-05-20	2022 07:23:09			
Vendor Details :							
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - College	Customer's Mod	bile 8097384	.039	Name :	Kedar Sir	
Address:							
Mumbai , , , , Mal	narashtra						
AMC Details :	_				_		
Expiry Date :	31-05-2021 12:00:00		Type:		Comprehensive		
Product Name:	Ppm						
Complain:	CCTV ,Biometric						
Technician Comment :	ppm done and one camera issue resolved by recrimping and one camera blurr dure to Somme lequid on lence wash only glass all done .						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	ppm done and one camera issue resolved by recrimping and one camera blurr dure to Somme lequid on lence wash only glass all done .						
Status History:	Date Time	Technician Nam	e Status	Remark		Sign	
	12-05-2022 04:40:46	Atique Salmani	Completed	ppm done and one camera issue resolved by recrimping and one camera blurr dure to Somme lequid on lence wash only glass all done .		Yfur	
	11-05-2022 07:23:27	Atique Salmani	New			-	
	11-05-2022 07:23:09	Atique Salmani	New			-	
Previous Complain	Date Time	me Technician Name		Remark			
History:	19-04-2022 11:10:26	Siddhesh Chavan	2 camera repair and ruten and install with poe infector and one power supply une in canteen and 1 main gate right side camera no video issue resolved switch side adapter reconnect and one server room camera no video issue resolved				
	10-03-2022 12:24:13	Ravi Rajbhar	15 camera issue resolved only switch side cannection issue main power and connect proper and ok working done and 304 / library camera no video issue resolved 6 RJ 45 connector used				