










# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5940</b>																																																		
<b>Priority :</b>	Low																																																	
<b>Created By :</b>	Admin - Apurva Vajaria																																																	
<b>Complaint Mob. No. :</b>	8097384039																																																	
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																																														
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	13-07-2022 10:29:11																																															
<b>Vendor Details :</b>																																																		
<b>Company Name/Client Name :</b>	Ritambhara Vishva Vidyapeeth - College	<b>Customer's Mobile :</b>	8097384039	<b>Name :</b>	Kedar Sir																																													
<b>Address :</b>																																																		
Mumbai , , , , Maharashtra																																																		
<b>AMC Details :</b>																																																		
<b>Expiry Date :</b>	31-05-2021 12:00:00		<b>Type :</b>	Comprehensive																																														
<b>Product Name :</b>	CCTV																																																	
<b>Complain :</b>	2 cameras not working 1 camera outside and 1 camera of staff																																																	
<b>Technician Comment :</b>	main road faulty camera replacement against new bullet camera install and ok working done class room 306 rj 45 connector replace																																																	
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																																	
<b>Remark :</b>	main road faulty camera replacement against new bullet camera install and ok working done class room 306 rj 45 connector replace																																																	
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-07-2022 12:27:01</td><td>Ravi Rajbhar</td><td>Completed</td><td>main road faulty camera replacement against new bullet camera install and ok working done class room 306 rj 45 connector replace</td><td></td></tr><tr><td>18-07-2022 09:55:00</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>16-07-2022 12:49:27</td><td>Ravi Rajbhar</td><td>Work Pending</td><td></td><td>-</td></tr><tr><td>15-07-2022 04:14:23</td><td>Ravi Rajbhar</td><td>Completed</td><td>one camera out side check but work pending bcz camera in side watter and camera remove and take to office</td><td></td></tr><tr><td>15-07-2022 10:40:14</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>13-07-2022 12:06:28</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>2 camera complaint but one camera issues resolved staff room and one camera out side pending bcz rain</td><td></td></tr><tr><td>13-07-2022 10:29:28</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>13-07-2022 10:29:11</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-07-2022 12:27:01	Ravi Rajbhar	Completed	main road faulty camera replacement against new bullet camera install and ok working done class room 306 rj 45 connector replace		18-07-2022 09:55:00	Ravi Rajbhar	New		-	16-07-2022 12:49:27	Ravi Rajbhar	Work Pending		-	15-07-2022 04:14:23	Ravi Rajbhar	Completed	one camera out side check but work pending bcz camera in side watter and camera remove and take to office		15-07-2022 10:40:14	Ravi Rajbhar	New		-	13-07-2022 12:06:28	Ravi Rajbhar	Work Pending	2 camera complaint but one camera issues resolved staff room and one camera out side pending bcz rain		13-07-2022 10:29:28	Ravi Rajbhar	New		-	13-07-2022 10:29:11	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																																														
18-07-2022 12:27:01	Ravi Rajbhar	Completed	main road faulty camera replacement against new bullet camera install and ok working done class room 306 rj 45 connector replace																																															
18-07-2022 09:55:00	Ravi Rajbhar	New		-																																														
16-07-2022 12:49:27	Ravi Rajbhar	Work Pending		-																																														
15-07-2022 04:14:23	Ravi Rajbhar	Completed	one camera out side check but work pending bcz camera in side watter and camera remove and take to office																																															
15-07-2022 10:40:14	Ravi Rajbhar	New		-																																														
13-07-2022 12:06:28	Ravi Rajbhar	Work Pending	2 camera complaint but one camera issues resolved staff room and one camera out side pending bcz rain																																															
13-07-2022 10:29:28	Ravi Rajbhar	New		-																																														
13-07-2022 10:29:11	Ravi Rajbhar	New		-																																														

Previous Complain History :			
	<b>Date Time</b>	<b>Technician Name</b>	<b>Remark</b>
	27-06-2022 01:35:11	Atique Salmani	Turf cameras back side recrimping working ok camera nmbr 50 47 restart working ok and camera nmbr 51 give saprete power and working ok.total 4 cameras issue resolved working ok.
	17-06-2022 11:05:40	Atique Salmani	3 cameras issue resolved fro rack SMPS unplugged which is use for injector 12 and 3rd floor and main gate camera cabling done 41 meter .all working ok