




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6408</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	8097384039																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	20-09-2022 11:06:59																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - College	Customer's Mobile :	8097384039	Name :	Kedar Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	second floor classroom camera again on off issue Third floor library 1 camera off issue																								
<b>Technician Comment :</b>	second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-09-2022 05:39:25</td><td>YogeshDesai</td><td>Completed</td><td>second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok</td><td></td></tr><tr><td>20-09-2022 11:07:18</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>20-09-2022 11:06:59</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-09-2022 05:39:25	YogeshDesai	Completed	second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok		20-09-2022 11:07:18	YogeshDesai	New		-	20-09-2022 11:06:59	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
20-09-2022 05:39:25	YogeshDesai	Completed	second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok																						
20-09-2022 11:07:18	YogeshDesai	New		-																					
20-09-2022 11:06:59	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-09-2022 10:07:46</td><td>YogeshDesai</td><td>Cash counter ground floor new ip dome camera installed Class no 208 second floor new ip dome camera installed Gymkhana on first floor 109 new ip dome camera installed faulty camera 3 rajen to office.</td></tr><tr><td>10-08-2022 12:26:17</td><td>Atique Salmani</td><td>1.Ritumbra 309/ 306 boath cameras ip was same so it was conflicting 2.Now changed room nmbr 309 ip is 192.168.1.135 Pass123456 And 306 ip is 192.168.1.211 Password 123456 3.And cash counter camera recrimping and delete then add working ok. 4.turf side camera recrimping and also I stalled new ip 66 box .</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-09-2022 10:07:46	YogeshDesai	Cash counter ground floor new ip dome camera installed Class no 208 second floor new ip dome camera installed Gymkhana on first floor 109 new ip dome camera installed faulty camera 3 rajen to office.	10-08-2022 12:26:17	Atique Salmani	1.Ritumbra 309/ 306 boath cameras ip was same so it was conflicting 2.Now changed room nmbr 309 ip is 192.168.1.135 Pass123456 And 306 ip is 192.168.1.211 Password 123456 3.And cash counter camera recrimping and delete then add working ok. 4.turf side camera recrimping and also I stalled new ip 66 box .											
Date Time	Technician Name	Remark																							
15-09-2022 10:07:46	YogeshDesai	Cash counter ground floor new ip dome camera installed Class no 208 second floor new ip dome camera installed Gymkhana on first floor 109 new ip dome camera installed faulty camera 3 rajen to office.																							
10-08-2022 12:26:17	Atique Salmani	1.Ritumbra 309/ 306 boath cameras ip was same so it was conflicting 2.Now changed room nmbr 309 ip is 192.168.1.135 Pass123456 And 306 ip is 192.168.1.211 Password 123456 3.And cash counter camera recrimping and delete then add working ok. 4.turf side camera recrimping and also I stalled new ip 66 box .																							