Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E : vallabhsecure@yah							
Service Status Det	tails: VE6633						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	8097384039						
Technician Name :	Ravi Rajbhar		Technici	ian Mobile 8080922965			
Ticket Type :	Complain	Date & Time :	19-10-2022 02:06:39				
Vendor Details :			•				
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - College	Customer's Mobil :	le 8097384039		Name:	Kedar Sir	
Address :		-					
Mumbai , , , , Mah	narashtra						
AMC Details :							
Expiry Date :	31-05-2021 12:00:00		Type:		Comprehensi	Comprehensive	
Product Name:	CCTV						
Complain :	old cameras are working so need to install in place of new						
Technician Comment :	two old camera return to office bcz check one old camera hondover to kedar sir and college 3 camera no video issue resolved main gate , office in side room, game room						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	two old camera return to office bcz check one old camera hondover to kedar sir and college 3 camera no video issue resolved main gate , office in side room, game room						
Status History:	Date Time	Technician Name	Status	Remark		Sign	
	19-10-2022 06:14:35	Ravi Rajbhar	Completed	two old camera return to office bcz check one old camera hondover to kedar sir and college 3 camera no video issue resolved main gate , office in side room, game room		fee .	
	19-10-2022 02:07:19	Ravi Rajbhar	New			-	
	19-10-2022 02:06:39	Ravi Rajbhar	New				
Previous Complain	Date Time	Technician Name	Remark				
History:	08-10-2022 10:49:36	Siddhesh Chavan	1 st floor exam room camera issue resolved and install new poe injector 3 floor 304 room camera poe injector install and camera issue resolved and working ok and 2 dc pin use				
	20-09-2022 11:06:59	YogeshDesai	second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok				