




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8350</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	8097384039																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	AMC visiting	<b>Date &amp; Time :</b>	15-05-2023 12:41:01																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Ritambhara Vishva Vidyapeeth - College	<b>Customer's Mobile :</b>	8097384039	<b>Name :</b>	Kedar Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	31-05-2021 12:00:00		<b>Type :</b>	Comprehensive																
<b>Product Name :</b>	Ppm																			
<b>Complain :</b>	CCTV PPM Need to do																			
<b>Technician Comment :</b>	Ppm done all out side camera also clean all working ok. One camera hub station insert water so need to changed bullet camera and some trees leaf coming front of camera main gate sontod to kedar sir for cut it .																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Ppm done all out side camera also clean all working ok. One camera hub station insert water so need to changed bullet camera and some trees leaf coming front of camera main gate sontod to kedar sir for cut it .																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-05-2023 05:40:08</td><td>Atique Salmani</td><td>Completed</td><td>Ppm done all out side camera also clean all working ok. One camera hub station insert water so need to changed bullet camera and some trees leaf coming front of camera main gate sontod to kedar sir for cut it .</td><td></td></tr><tr><td>15-05-2023 12:41:38</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-05-2023 05:40:08	Atique Salmani	Completed	Ppm done all out side camera also clean all working ok. One camera hub station insert water so need to changed bullet camera and some trees leaf coming front of camera main gate sontod to kedar sir for cut it .		15-05-2023 12:41:38	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
15-05-2023 05:40:08	Atique Salmani	Completed	Ppm done all out side camera also clean all working ok. One camera hub station insert water so need to changed bullet camera and some trees leaf coming front of camera main gate sontod to kedar sir for cut it .																	
15-05-2023 12:41:38	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-04-2023 02:09:18</td><td>Prashant Nikalje</td><td>prashant old 26.04.2023 visited site smart office biomax software setting done given software traning</td></tr><tr><td>08-04-2023 10:27:07</td><td>Ravi Rajbhar</td><td>backside out side one no video issue resolved but temporary going on in nvr bcz one pair cable breck inform to kedar sir next time need to change cable camera off 21/3 /23</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-04-2023 02:09:18	Prashant Nikalje	prashant old 26.04.2023 visited site smart office biomax software setting done given software traning	08-04-2023 10:27:07	Ravi Rajbhar	backside out side one no video issue resolved but temporary going on in nvr bcz one pair cable breck inform to kedar sir next time need to change cable camera off 21/3 /23						
Date Time	Technician Name	Remark																		
26-04-2023 02:09:18	Prashant Nikalje	prashant old 26.04.2023 visited site smart office biomax software setting done given software traning																		
08-04-2023 10:27:07	Ravi Rajbhar	backside out side one no video issue resolved but temporary going on in nvr bcz one pair cable breck inform to kedar sir next time need to change cable camera off 21/3 /23																		