







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9464																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8097384039																								
Technician Name :	Munna Gupta	Technician Mobile :	8080922982																						
Ticket Type :	Complain	Date & Time :	08-09-2023 10:46:29																						
Vendor Details :																									
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - School	Customer's Mobile :	8097384039	Name :	Kedar Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-05-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	2nd floor switch need to change and new switch need to collect																								
Technician Comment :	Second floor switch repair and return and installed. All cctv system working ok																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Second floor switch repair and return and installed. All cctv system working ok																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-09-2023 01:10:22</td><td>Munna Gupta</td><td>Completed</td><td>Second floor switch repair and return and installed. All cctv system working ok</td><td></td></tr><tr><td>08-09-2023 01:10:13</td><td>Munna Gupta</td><td>Completed</td><td>Second floor switch repair and return and installed. All cctv system working ok</td><td></td></tr><tr><td>08-09-2023 10:46:37</td><td>Munna Gupta</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-09-2023 01:10:22	Munna Gupta	Completed	Second floor switch repair and return and installed. All cctv system working ok		08-09-2023 01:10:13	Munna Gupta	Completed	Second floor switch repair and return and installed. All cctv system working ok		08-09-2023 10:46:37	Munna Gupta	New		-
Date Time	Technician Name	Status	Remark	Sign																					
08-09-2023 01:10:22	Munna Gupta	Completed	Second floor switch repair and return and installed. All cctv system working ok																						
08-09-2023 01:10:13	Munna Gupta	Completed	Second floor switch repair and return and installed. All cctv system working ok																						
08-09-2023 10:46:37	Munna Gupta	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-08-2023 01:19:54</td><td>Ravi Rajbhar</td><td>back side one camera box cover fitted</td></tr><tr><td>18-08-2023 03:05:56</td><td>Atique Salmani</td><td>School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-08-2023 01:19:54	Ravi Rajbhar	back side one camera box cover fitted	18-08-2023 03:05:56	Atique Salmani	School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.											
Date Time	Technician Name	Remark																							
19-08-2023 01:19:54	Ravi Rajbhar	back side one camera box cover fitted																							
18-08-2023 03:05:56	Atique Salmani	School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.																							