







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13879																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9819121121																																		
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																															
Ticket Type :	Complain	Date & Time :	21-01-2025 10:38:56																																
Vendor Details :																																			
Company Name/Client Name :	KES International School	Customer's Mobile :	9819121121	Name :	Keval Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	School outdoor bullet camera not working.																																		
Technician Comment :	One Bullat camera repair return with install and ok working done and cmaera ip 192.168.1.138 Password client side created by tejas sir																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	One Bullat camera repair return with install and ok working done and cmaera ip 192.168.1.138 Password client side created by tejas sir																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-01-2025 04:52:31</td><td>Ravi Rajbhar</td><td>Completed</td><td>One Bullat camera repair return with install and ok working done and cmaera ip 192.168.1.138 Password client side created by tejas sir</td><td></td></tr><tr><td>29-01-2025 10:36:50</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>28-01-2025 10:37:08</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>21-01-2025 10:44:56</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>one camera not working and colleted the camera.chek the office.</td><td></td></tr><tr><td>21-01-2025 10:43:14</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-01-2025 04:52:31	Ravi Rajbhar	Completed	One Bullat camera repair return with install and ok working done and cmaera ip 192.168.1.138 Password client side created by tejas sir		29-01-2025 10:36:50	Ravi Rajbhar	New		-	28-01-2025 10:37:08	Ravi Rajbhar	New		-	21-01-2025 10:44:56	Ravi Rajbhar	Work Pending	one camera not working and colleted the camera.chek the office.		21-01-2025 10:43:14	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
29-01-2025 04:52:31	Ravi Rajbhar	Completed	One Bullat camera repair return with install and ok working done and cmaera ip 192.168.1.138 Password client side created by tejas sir																																
29-01-2025 10:36:50	Ravi Rajbhar	New		-																															
28-01-2025 10:37:08	Ravi Rajbhar	New		-																															
21-01-2025 10:44:56	Ravi Rajbhar	Work Pending	one camera not working and colleted the camera.chek the office.																																
21-01-2025 10:43:14	Ravi Rajbhar	New		-																															

Previous Complain History :			
	Date Time	Technician Name	Remark
	08-10-2024 04:25:35	Ravi Rajbhar	Ground floor one cmaera out side cable need to change 80-100 Aprox (keval sir told camera cable changing to client side i am infrom to swapnil sir but swapnil sir saying put on email.drop And ezview software 32 chanal cmaera viewing ok done auto sequence done
	05-10-2024 12:13:44	ChandanYadav	Car lift 4 camera angle sitting done. Car lift 1 transmitter adapter install done.