

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13988																																													
Priority :	Low																																												
Created By :	Admin - Apurva Vajaria																																												
Complaint Mob. No. :	9819121121																																												
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																																									
Ticket Type :	Complain	Date & Time :	01-02-2025 10:29:30																																										
Vendor Details :																																													
Company Name/Client Name :	KES International School	Customer's Mobile :	9819121121	Name :	Keval Sir																																								
Address :																																													
Mumbai , , , , Maharashtra																																													
AMC Details :																																													
Expiry Date :	01-01-1970 05:30:00		Type :																																										
Product Name :	CCTV																																												
Complain :	school's main entrance Gate no 2 camera shows a blur view																																												
Technician Comment :	main gate entry gate no 2 camera install and working ok.																																												
Complain Operator :	Desktop - Apurva Vajaria																																												
Remark :	main gate entry gate no 2 camera install and working ok.																																												
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-03-2025 02:03:49</td><td>ChandanYadav</td><td>Completed</td><td>main gate entry gate no 2 camera install and working ok.</td><td></td></tr><tr><td>04-03-2025 12:05:42</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>08-02-2025 10:42:44</td><td>ChandanYadav</td><td>Awaiting Spares</td><td>Main gate bullet camera disturbance issue changed new rj 45 connector but same issue so collect camera for check .</td><td></td></tr><tr><td>08-02-2025 10:23:22</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>06-02-2025 01:28:06</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>03-02-2025 11:31:13</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>01-02-2025 10:29:37</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-03-2025 02:03:49	ChandanYadav	Completed	main gate entry gate no 2 camera install and working ok.		04-03-2025 12:05:42	ChandanYadav	New		-	08-02-2025 10:42:44	ChandanYadav	Awaiting Spares	Main gate bullet camera disturbance issue changed new rj 45 connector but same issue so collect camera for check .		08-02-2025 10:23:22	ChandanYadav	New		-	06-02-2025 01:28:06	ChandanYadav	New		-	03-02-2025 11:31:13	ChandanYadav	New		-	01-02-2025 10:29:37	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																																									
04-03-2025 02:03:49	ChandanYadav	Completed	main gate entry gate no 2 camera install and working ok.																																										
04-03-2025 12:05:42	ChandanYadav	New		-																																									
08-02-2025 10:42:44	ChandanYadav	Awaiting Spares	Main gate bullet camera disturbance issue changed new rj 45 connector but same issue so collect camera for check .																																										
08-02-2025 10:23:22	ChandanYadav	New		-																																									
06-02-2025 01:28:06	ChandanYadav	New		-																																									
03-02-2025 11:31:13	ChandanYadav	New		-																																									
01-02-2025 10:29:37	ChandanYadav	New		-																																									

Previous Complain History :			
	Date Time	Technician Name	Remark
	21-01-2025 10:38:56	Ravi Rajbhar	One Bullat camera repair return with install and ok working done and cmaera ip 192.168.1.138 Password client side created by tejas sir
	08-10-2024 04:25:35	Ravi Rajbhar	Ground floor one cmaera out side cable need to change 80-100 Aprox (keval sir told camera cable changing to client side i am infrom to swapnil sir but swapnil sir saying put on email.drop And ezview software 32 chanal cmaera viewing ok done auto sequence done