Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE12211								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9819121121							
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842				
Ticket Type:	Complain	Date & Time :	23-07-2024 10:56:46	07-2024 10:56:46				
Vendor Details :								
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir			
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name:	CCTV							
Complain:	Site: Mantri Park Goregaon - refuge camera need to check and outside cameras need to check							
Technician Comment :	Levender All camera working and one camera cable faulty levender loby change the cable. Lilly. 1.8 floor Refuges ariya camera working and cable faulty matter room cable joined chenge the cable and 8 floor Refuges ariya camera not working. 2. Back side camera damage. 3. Main gate back side camera working. 4.lobby camera change the cable and cable faulty. 5.Main gate back side two camera not working.one camera are working and one camera faulty cheking the office. 6.Main gate two new 4*4 box installation							
Complain Operator :	Desktop - Apurva Vajaria							
Remark :	Levender All camera working and one camera cable faulty levender loby change the cable. Lilly. 1.8 floor Refuges ariya camera working and cable faulty matter room cable joined chenge the cable and 8 floor Refuges ariya camera not working. 2. Back side camera damage. 3. Main gate back side camera working. 4.lobby camera change the cable and cable faulty. 5.Main gate back side two camera not working.one camera are working and one camera faulty cheking the office. 6.Main gate two new 4*4 box installation							

Status History	Date Time	Technician Name	Status	Remark	Sign	
•	23-07-2024 05:18:25	ChandanYadav	Work Pending	Levender All camera working and one camera cable faulty levender loby change the cable. Lilly. 1.8 floor Refuges ariya camera working and cable faulty matter room cable joined chenge the cable and 8 floor Refuges ariya camera not working. 2. Back side camera damage. 3. Main gate back side camera working. 4.lobby camera change the cable and cable faulty. 5.Main gate back side two camera not working.one camera are working and one camera faulty cheking the office. 6.Main gate two new 4*4 box installation	Bal	
	23-07-2024 10:56:52	ChandanYadav	New		-	
Previous Complain History :	Date Time	Technician Name		Remark		
	27-08-2024 12:32:27	ChandanYadav	bullon 3)Re 4)Hdd.1 tb box require start date.1 1)Lilly one and chekin camera cor	Lupin 1)One camera cleaning 2)One camera problem requirment video bullon 3)Recording start date.17/8/24 4)Recording end date.27/8/24 4)Hdd.1 tb Orchid 1)Back side one camera angle sitting and one 4*4 box requirment. 2)15th floor Refuges camera working ok 3) Recording start date.17/7/24 4) Recording end date.27/8/24 5)4tb hdd Lilly 1)Lilly one main gate side camera not working and camera problem and cheking the office. Levender 1) All camera working ok 2)All camera connected Hikvision NVR store room. 3) Hikvision NVR 4tb hdd connected 4) Recording start date 18/8/24 5) Recording end date 27/8/24?		
	20-08-2024 12:13:17	ChandanYadav	All camera working ok and swich hanging problem solve and camera working ok. Cctv working ok.			