

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5183																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9819121121																													
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																										
Ticket Type :	New Installation	Date & Time :	12-04-2022 10:24:57																											
Vendor Details :																														
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	site: Arika Dindoshi Goregaon - CCTV Installation																													
Technician Comment :	16 channel dvr.4 power supply. 14 camera and 2u ruck installation. cctv working ok																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	16 channel dvr.4 power supply. 14 camera and 2u ruck installation. cctv working ok																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-04-2022 04:37:36</td><td>ChandanYadav</td><td>Completed</td><td>16 channel dvr.4 power supply. 14 camera and 2u ruck installation. cctv working ok</td><td></td></tr><tr><td>30-04-2022 10:28:08</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>12-04-2022 10:25:14</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>12-04-2022 10:24:58</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-04-2022 04:37:36	ChandanYadav	Completed	16 channel dvr.4 power supply. 14 camera and 2u ruck installation. cctv working ok		30-04-2022 10:28:08	ChandanYadav	New		-	12-04-2022 10:25:14	ChandanYadav	New		-	12-04-2022 10:24:58	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																										
30-04-2022 04:37:36	ChandanYadav	Completed	16 channel dvr.4 power supply. 14 camera and 2u ruck installation. cctv working ok																											
30-04-2022 10:28:08	ChandanYadav	New		-																										
12-04-2022 10:25:14	ChandanYadav	New		-																										
12-04-2022 10:24:58	ChandanYadav	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-04-2022 04:16:18</td><td>ChandanYadav</td><td>8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.</td></tr><tr><td>28-04-2022 01:45:50</td><td>Munna Gupta</td><td>I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-04-2022 04:16:18	ChandanYadav	8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.	28-04-2022 01:45:50	Munna Gupta	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																
Date Time	Technician Name	Remark																												
29-04-2022 04:16:18	ChandanYadav	8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.																												
28-04-2022 01:45:50	Munna Gupta	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																												