




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5322																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9819121121																								
Technician Name :	Munna Gupta		Technician Mobile :	8080922982																					
Ticket Type :	Complain	Date & Time :	28-04-2022 01:45:50																						
Vendor Details :																									
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	cCTV-Intercom																								
Complain :	site: suman tower - c wing 302 intercom issue and 2 camera issue																								
Technician Comment :	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-04-2022 01:55:47</td><td>Munna Gupta</td><td>Completed</td><td>I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.</td><td></td></tr><tr><td>28-04-2022 01:46:06</td><td>Munna Gupta</td><td>New</td><td></td><td>-</td></tr><tr><td>28-04-2022 01:45:50</td><td>Munna Gupta</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-04-2022 01:55:47	Munna Gupta	Completed	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.		28-04-2022 01:46:06	Munna Gupta	New		-	28-04-2022 01:45:50	Munna Gupta	New		-
Date Time	Technician Name	Status	Remark	Sign																					
28-04-2022 01:55:47	Munna Gupta	Completed	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																						
28-04-2022 01:46:06	Munna Gupta	New		-																					
28-04-2022 01:45:50	Munna Gupta	New		-																					

Previous Complain History :			
	Date Time	Technician Name	Remark
	27-04-2022 03:59:36	ChandanYadav	16 channel dvr new installation and 4 tb hard disk install. all camera working ok .
	23-04-2022 06:39:47	ChandanYadav	5 camera installation and 3 camera pending