

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8448																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9821069152																								
Technician Name :	Kalpesh Subhash Gurav		Technician Mobile :	8879684054																					
Ticket Type :	Complain	Date & Time :	29-05-2023 05:15:03																						
Vendor Details :																									
Company Name/Client Name :	Swapnalok CHS	Customer's Mobile :	9821069152	Name :	Kishor Bhai																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																					
Product Name :	Intercom																								
Complain :	intercom display some noise issue																								
Technician Comment :	Display Problem Solved A Wing 502- Two Parson Finger Add OK. B Wing 503- Two Parson Finger Add OK.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Display Problem Solved A Wing 502- Two Parson Finger Add OK. B Wing 503- Two Parson Finger Add OK.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-05-2023 11:37:26</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Display Problem Solved A Wing 502- Two Parson Finger Add OK. B Wing 503- Two Parson Finger Add OK.</td><td></td></tr><tr><td>29-05-2023 05:17:35</td><td>Kalpesh SubhashGurav</td><td>Awaiting Spares</td><td>Security Display Issue Pending Required IC</td><td></td></tr><tr><td>29-05-2023 05:15:26</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-05-2023 11:37:26	Kalpesh SubhashGurav	Completed	Display Problem Solved A Wing 502- Two Parson Finger Add OK. B Wing 503- Two Parson Finger Add OK.		29-05-2023 05:17:35	Kalpesh SubhashGurav	Awaiting Spares	Security Display Issue Pending Required IC		29-05-2023 05:15:26	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
30-05-2023 11:37:26	Kalpesh SubhashGurav	Completed	Display Problem Solved A Wing 502- Two Parson Finger Add OK. B Wing 503- Two Parson Finger Add OK.																						
29-05-2023 05:17:35	Kalpesh SubhashGurav	Awaiting Spares	Security Display Issue Pending Required IC																						
29-05-2023 05:15:26	Kalpesh SubhashGurav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-05-2023 11:34:22</td><td>Kalpesh SubhashGurav</td><td>Security Display Problem Solved. 2401 Video Door Phone Problem Solved.</td></tr><tr><td>08-05-2023 11:47:57</td><td>Prashant Nikalje</td><td>06.05.23 prashant old visited site d23 camera off issued resolved camera under the observation . 08.05.2023 d23 water tank camera issue resolved re crimping rj45 connector switch side camera under the observation</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-05-2023 11:34:22	Kalpesh SubhashGurav	Security Display Problem Solved. 2401 Video Door Phone Problem Solved.	08-05-2023 11:47:57	Prashant Nikalje	06.05.23 prashant old visited site d23 camera off issued resolved camera under the observation . 08.05.2023 d23 water tank camera issue resolved re crimping rj45 connector switch side camera under the observation											
Date Time	Technician Name	Remark																							
20-05-2023 11:34:22	Kalpesh SubhashGurav	Security Display Problem Solved. 2401 Video Door Phone Problem Solved.																							
08-05-2023 11:47:57	Prashant Nikalje	06.05.23 prashant old visited site d23 camera off issued resolved camera under the observation . 08.05.2023 d23 water tank camera issue resolved re crimping rj45 connector switch side camera under the observation																							