


# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE11556</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9820606496				
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	04-05-2024 03:21:43		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	Samet Sikhar Mahal Society	<b>Customer's Mobile :</b>	9820606496	<b>Name :</b>	Kothari
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>		
<b>Product Name :</b>	VDP				
<b>Complain :</b>	flat no. 1002/1704/301/1703/1103(8976363892)/701- VDP Issue (Note flat no. 701 after 1 week need to send)				
<b>Technician Comment :</b>	1704 = working ok 1002 = working ok 301 = working ok 1703 = door lock 1103 = working ok spker slow voice 701 = flat lock 1502 = working ok 1203 = lobby cable issue 1601 = working ok 1004= working ok 403 = vdp reinstalling pending clint side 1603 1604 = working ok				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	1704 = working ok 1002 = working ok 301 = working ok 1703 = door lock 1103 = working ok spker slow voice 701 = flat lock 1502 = working ok 1203 = lobby cable issue 1601 = working ok 1004= working ok 403 = vdp reinstalling pending clint side 1603 1604 = working ok				
<b>Status History :</b>	<b>Date Time</b>	<b>Technician Name</b>	<b>Status</b>	<b>Remark</b>	<b>Sign</b>
	21-06-2024 11:15:36	Siddhesh Chavan	New		-
	08-05-2024 03:51:39	Siddhesh Chavan	Work Pending	1704 = working ok 1002 = working ok 301 = working ok 1703 = door lock 1103 = working ok spker slow voice 701 = flat lock 1502 = working ok 1203 = lobby cable issue 1601 = working ok 1004= working ok 403 = vdp reinstalling pending clint side 1603 1604 = working ok	
	08-05-2024 11:23:27	Siddhesh Chavan	New		-

Previous Complain History :			
	Date Time	Technician Name	Remark
	08-06-2024 10:18:15	Siddhesh Chavan	17 th floor distubter change and issue resoved
	12-04-2024 10:58:09	Siddhesh Chavan	903 out door camera install and issue resoved 603 lobby video cable issue nc01 issue