







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6443</b>																																													
<b>Priority :</b>	Low																																												
<b>Created By :</b>	Admin - Apurva Vajaria																																												
<b>Complaint Mob. No. :</b>	9820606496																																												
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																																									
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	24-09-2022 05:07:21																																										
<b>Vendor Details :</b>																																													
Company Name/Client Name :	Samdeshekhar Society	Customer's Mobile :	9820606496	Name :	Kothari																																								
<b>Address :</b>																																													
Mumbai , , , , Maharashtra																																													
<b>AMC Details :</b>																																													
Expiry Date :	01-01-1970 05:30:00		Type :																																										
<b>Product Name :</b>	VDP																																												
<b>Complain :</b>	1901 - vdp and outdoor camera issue need to check 201 - VDP not working																																												
<b>Technician Comment :</b>	1901 new out door camera install and vdp install and lobby video working ok and out camera working ok and old vdp and out door camera handover to Clint																																												
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																												
<b>Remark :</b>	1901 new out door camera install and vdp install and lobby video working ok and out camera working ok and old vdp and out door camera handover to Clint																																												
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-01-2023 07:06:29</td><td>Siddhesh Chavan</td><td>Completed</td><td>1901 new out door camera install and vdp install and lobby video working ok and out camera working ok and old vdp and out door camera handover to Clint</td><td></td></tr><tr><td>16-01-2023 05:43:27</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>27-09-2022 08:44:39</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>201 vdp working ok and 1901 vdp take to office for checking</td><td></td></tr><tr><td>26-09-2022 06:05:28</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>26-09-2022 06:05:22</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>24-09-2022 05:07:35</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>24-09-2022 05:07:21</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-01-2023 07:06:29	Siddhesh Chavan	Completed	1901 new out door camera install and vdp install and lobby video working ok and out camera working ok and old vdp and out door camera handover to Clint		16-01-2023 05:43:27	Siddhesh Chavan	New		-	27-09-2022 08:44:39	Siddhesh Chavan	Work Pending	201 vdp working ok and 1901 vdp take to office for checking		26-09-2022 06:05:28	Siddhesh Chavan	New		-	26-09-2022 06:05:22	Siddhesh Chavan	New		-	24-09-2022 05:07:35	Siddhesh Chavan	New		-	24-09-2022 05:07:21	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																																									
16-01-2023 07:06:29	Siddhesh Chavan	Completed	1901 new out door camera install and vdp install and lobby video working ok and out camera working ok and old vdp and out door camera handover to Clint																																										
16-01-2023 05:43:27	Siddhesh Chavan	New		-																																									
27-09-2022 08:44:39	Siddhesh Chavan	Work Pending	201 vdp working ok and 1901 vdp take to office for checking																																										
26-09-2022 06:05:28	Siddhesh Chavan	New		-																																									
26-09-2022 06:05:22	Siddhesh Chavan	New		-																																									
24-09-2022 05:07:35	Siddhesh Chavan	New		-																																									
24-09-2022 05:07:21	Siddhesh Chavan	New		-																																									

Previous Complain History :	Date Time	Technician Name	Remark
	24-01-2023 05:54:53	Siddhesh Chavan	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue
	24-01-2023 05:53:58	Siddhesh Chavan	vdp working ok lobby video working ok ding dong bell issue