




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7411																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9820606496																													
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																										
Ticket Type :	Complain	Date & Time :	19-01-2023 11:02:29																											
Vendor Details :																														
Company Name/Client Name :	Samdeshekhar Society	Customer's Mobile :	9820606496	Name :	Kothari																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	Flat no. 1701 lobby video not able to view																													
Technician Comment :	1701 one to working ok and lobby cable issue need to change cable																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	1701 one to working ok and lobby cable issue need to change cable																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-01-2023 12:08:55</td><td>Siddhesh Chavan</td><td>Completed</td><td>1701 one to working ok and lobby cable issue need to change cable</td><td></td></tr><tr><td>20-01-2023 10:43:21</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>19-01-2023 11:07:56</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>1701 lobby video issue need to check lobby cable</td><td></td></tr><tr><td>19-01-2023 11:02:35</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-01-2023 12:08:55	Siddhesh Chavan	Completed	1701 one to working ok and lobby cable issue need to change cable		20-01-2023 10:43:21	Siddhesh Chavan	New		-	19-01-2023 11:07:56	Siddhesh Chavan	Work Pending	1701 lobby video issue need to check lobby cable		19-01-2023 11:02:35	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
20-01-2023 12:08:55	Siddhesh Chavan	Completed	1701 one to working ok and lobby cable issue need to change cable																											
20-01-2023 10:43:21	Siddhesh Chavan	New		-																										
19-01-2023 11:07:56	Siddhesh Chavan	Work Pending	1701 lobby video issue need to check lobby cable																											
19-01-2023 11:02:35	Siddhesh Chavan	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-01-2023 05:54:53</td><td>Siddhesh Chavan</td><td>vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue</td></tr><tr><td>24-01-2023 05:53:58</td><td>Siddhesh Chavan</td><td>vdp working ok lobby video working ok ding dong bell issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-01-2023 05:54:53	Siddhesh Chavan	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue	24-01-2023 05:53:58	Siddhesh Chavan	vdp working ok lobby video working ok ding dong bell issue																
Date Time	Technician Name	Remark																												
24-01-2023 05:54:53	Siddhesh Chavan	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue																												
24-01-2023 05:53:58	Siddhesh Chavan	vdp working ok lobby video working ok ding dong bell issue																												