




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7450																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820606496																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	24-01-2023 05:54:53																	
Vendor Details :																				
Company Name/Client Name :	Samdeshekhar Society	Customer's Mobile :	9820606496	Name :	Kothari															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	VDP																			
Complain :	1701 - vdp issue																			
Technician Comment :	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-01-2023 06:47:11</td><td>Siddhesh Chavan</td><td>Completed</td><td>vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue</td><td></td></tr><tr><td>24-01-2023 05:55:00</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-01-2023 06:47:11	Siddhesh Chavan	Completed	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue		24-01-2023 05:55:00	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
24-01-2023 06:47:11	Siddhesh Chavan	Completed	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue																	
24-01-2023 05:55:00	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-01-2023 05:53:58</td><td>Siddhesh Chavan</td><td>vdp working ok lobby video working ok ding dong bell issue</td></tr><tr><td>19-01-2023 11:02:29</td><td>Siddhesh Chavan</td><td>1701 one to working ok and lobby cable issue need to change cable</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-01-2023 05:53:58	Siddhesh Chavan	vdp working ok lobby video working ok ding dong bell issue	19-01-2023 11:02:29	Siddhesh Chavan	1701 one to working ok and lobby cable issue need to change cable						
Date Time	Technician Name	Remark																		
24-01-2023 05:53:58	Siddhesh Chavan	vdp working ok lobby video working ok ding dong bell issue																		
19-01-2023 11:02:29	Siddhesh Chavan	1701 one to working ok and lobby cable issue need to change cable																		