




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE979</b>																									
<b>Priority :</b>	High																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820606496																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	24-01-2020 03:23:30																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Samet Sikhar Mahal Society	Customer's Mobile :	9820606496	Name :	Kothari																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	issue is Flat no:1304																								
<b>Technician Comment :</b>	1304 lobby vewing issue there screen shifted by electrician so he didn't connect the nc01 so it was not vewing and also some communication issue so factory reset the screen now working proper ok .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	1304 lobby vewing issue there screen shifted by electrician so he didn't connect the nc01 so it was not vewing and also some communication issue so factory reset the screen now working proper ok .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-01-2020 05:13:54</td><td>Atique Salmani</td><td>Completed</td><td>1304 lobby vewing issue there screen shifted by electrician so he didn't connect the nc01 so it was not vewing and also some communication issue so factory reset the screen now working proper ok .</td><td></td></tr><tr><td>24-01-2020 03:23:37</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>24-01-2020 03:23:31</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-01-2020 05:13:54	Atique Salmani	Completed	1304 lobby vewing issue there screen shifted by electrician so he didn't connect the nc01 so it was not vewing and also some communication issue so factory reset the screen now working proper ok .		24-01-2020 03:23:37	Atique Salmani	New		-	24-01-2020 03:23:31	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-01-2020 05:13:54	Atique Salmani	Completed	1304 lobby vewing issue there screen shifted by electrician so he didn't connect the nc01 so it was not vewing and also some communication issue so factory reset the screen now working proper ok .																						
24-01-2020 03:23:37	Atique Salmani	New		-																					
24-01-2020 03:23:31	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-05-2023 04:49:21</td><td>Kalpesh SubhashGurav</td><td>VDP Faulty and return back</td></tr><tr><td>26-05-2023 04:47:39</td><td>Kalpesh SubhashGurav</td><td>VDP And Out Door Camera Faulty and return back</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-05-2023 04:49:21	Kalpesh SubhashGurav	VDP Faulty and return back	26-05-2023 04:47:39	Kalpesh SubhashGurav	VDP And Out Door Camera Faulty and return back											
Date Time	Technician Name	Remark																							
26-05-2023 04:49:21	Kalpesh SubhashGurav	VDP Faulty and return back																							
26-05-2023 04:47:39	Kalpesh SubhashGurav	VDP And Out Door Camera Faulty and return back																							