




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11559																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930943918																			
Technician Name :	Prashant Saroj		Technician Mobile :	9519795009																
Ticket Type :	Complain	Date & Time :	06-05-2024 10:14:38																	
Vendor Details :																				
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	Outside main gate Both cameras not working																			
Technician Comment :	Main gate (2) camera off issue done																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Main gate (2) camera off issue done																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-05-2024 12:44:58</td><td>PrashantSaroj</td><td>Completed</td><td>Main gate (2) camera off issue done</td><td></td></tr><tr><td>06-05-2024 10:14:45</td><td>PrashantSaroj</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-05-2024 12:44:58	PrashantSaroj	Completed	Main gate (2) camera off issue done		06-05-2024 10:14:45	PrashantSaroj	New		-
Date Time	Technician Name	Status	Remark	Sign																
06-05-2024 12:44:58	PrashantSaroj	Completed	Main gate (2) camera off issue done																	
06-05-2024 10:14:45	PrashantSaroj	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-06-2024 11:12:20</td><td>Neeraj Chauhan</td><td>1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done</td></tr><tr><td>20-06-2024 12:35:14</td><td>Neeraj Chauhan</td><td>4/4 box 5 nos install and lift camera check power supply issue and out side 1 camera pipe fittings and 3 Camera angle set</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-06-2024 11:12:20	Neeraj Chauhan	1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done	20-06-2024 12:35:14	Neeraj Chauhan	4/4 box 5 nos install and lift camera check power supply issue and out side 1 camera pipe fittings and 3 Camera angle set						
Date Time	Technician Name	Remark																		
24-06-2024 11:12:20	Neeraj Chauhan	1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done																		
20-06-2024 12:35:14	Neeraj Chauhan	4/4 box 5 nos install and lift camera check power supply issue and out side 1 camera pipe fittings and 3 Camera angle set																		