## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE11891 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 9930943918 Mob. No. : Technician Atique Salmani **Technician Mobile :** 8080922984 Name : Complain Date & Time : 14-06-2024 10:55:47 **Ticket Type : Vendor Details :** Company St Joseph Customer's Mobile 9930943918 Name : Levon Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name** CCTV **Complain** : newly installed cameras sometime getting off and recording issue and DVR 161 camera no. 2 off issue and outside gate camera some issue Technician Maine gate SMPS changed against faulty and clarity issue resolved but all 5 box need to changed **Comment**: and BNC dc also and 163 cameranmbr 2 need to collect there is bus park 7 floor newly dome camera need to shift according to Leone sir . Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Maine gate SMPS changed against faulty and clarity issue resolved but all 5 box need to changed and BNC dc also and 163 cameranmbr 2 need to collect there is bus park 7 floor newly dome camera need to shift according to Leone sir . **Status History** Date Time **Technician Name** Remark Status Sign : 25-06-2024 Atique Salmani Completed 01:33:01 15-06-2024 Atique Salmani New 10:54:50 14-06-2024 Atique Salmani Work Pending Maine gate SMPS changed 12:47:36 against faulty and clarity issue resolved but all 5 box need to changed and BNC dc also and 163 cameranmbr 2 need to collect there is bus park 7 floor newly dome camera need to shift according to Leone sir . 14-06-2024 Atique Salmani New 10:55:53

Previous Complain History :	Date Time	Technician Name	Remark
	24-06-2024 11:12:20	Neeraj Chauhan	1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done
	20-06-2024 12:35:14	Neeraj Chauhan	$4/4~{\rm box}~5$ nos install and lift camera check power supply issue and out side 1 camera pipe fittings and 3 Camera angle set