## Vallabh Enterprises

**Regd. Office** : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE11973 Low **Priority** : **Created By :** Admin - Apurva Vajaria Complaint 9930943918 Mob. No. : Technician Neeraj Chauhan **Technician Mobile :** 8898885764 Name : Complain Date & Time : 24-06-2024 11:12:20 **Ticket Type :** Vendor Details : St Joseph Customer's Mobile 9930943918 Company Name : Levon Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name** CCTV 1)NVR 156 1 cam issue (Gr flr) 2)DVR 157 2 cam disturbance (outside main gate) 3)DVR 158 class **Complain**: no 11 Disturbance 4)DVR 159 new lift cam issue 5)DVR 161 cam 2 and 8 Disturbance 6)DVR 163 2 cameras disturbance 7)DVR 165 need to adjust view of 2 camera Technician 1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side **Comment**: reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done Complain Desktop - Apurva Vajaria **Operator** : 1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate **Remark** : camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done

Status History :	Date Time	Technician Name	Status	Remark	Sign
	24-06-2024 06:57:41	Neeraj Chauhan	Work Pending	1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done	A Dory J'
	24-06-2024 11:12:27	Neeraj Chauhan	New		-
Previous Complain History :	Date Time			Technician Name	Remark
	26-11-2024 11:36:30				
	21-11-2024 04:05:51			Siddhesh Chavan	