

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14921															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9930943918														
Technician Name :	Atique Salmani		Technician Mobile :	8080922984											
Ticket Type :	Complain	Date & Time :	05-06-2025 11:05:20												
Vendor Details :															
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon										
Address :															
Mumbai , , , , Maharashtra															
AMC Details :															
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive											
Product Name :	CCTV														
Complain :	1. Camera 5&6 frm NVR 162 to be moved to NVR 166 2. New camera 1st flr ofc and new camera 2nd flr ofc to be added to NVR 162 3. 2 IP cameras of NVR 151, wires were cut for ofc renovation work, can now be connected to the POE switch of 2nd flr ofc														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-06-2025 11:05:25</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-06-2025 11:05:25	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign											
05-06-2025 11:05:25	Atique Salmani	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-07-2025 11:23:55</td><td>Neeraj Chauhan</td><td>Power supply changed issue resolved and faulty collected</td></tr><tr><td>30-06-2025 05:27:09</td><td>Atique Salmani</td><td>Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.153 2nd 4 floor corridor 154 cameranmbr 6 7 floor corridor angel set Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-07-2025 11:23:55	Neeraj Chauhan	Power supply changed issue resolved and faulty collected	30-06-2025 05:27:09	Atique Salmani	Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.153 2nd 4 floor corridor 154 cameranmbr 6 7 floor corridor angel set Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.	
Date Time	Technician Name	Remark													
01-07-2025 11:23:55	Neeraj Chauhan	Power supply changed issue resolved and faulty collected													
30-06-2025 05:27:09	Atique Salmani	Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.153 2nd 4 floor corridor 154 cameranmbr 6 7 floor corridor angel set Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.													