## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE15319								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9930943918							
Technician Name :	Atique Salmani		Te:	chni	cian Mobile 8080922984			
Ticket Type :	Complain	Complain Date & Time:		21-07-2025 10:57:04				
Vendor Details :	Details:							
Company Name/Client Name :	St Joseph	Customer's Mobi :	ile 99	3094	3918	Name :	Levon	
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	31-03-2021 12:00:00		Ty	Type:		Non-Comprehensive		
<b>Product Name:</b>	CCTV							
Complain :	One new camera needs to be installed in the fee office ground floor (corner above the door) - Survey need to do for cabling							
Technician Comment :	From fee counter to ground floor lift cabling required 30 metr cabling and ground floor lift rack reqired poe swich + plug point .and camera need to add in nvr 166 according to leone sir							k
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	From fee counter to ground floor lift cabling required 30 metr cabling and ground floor lift rack reqired poe swich + plug point .and camera need to add in nvr 166 according to leone sir							
<b>Status History :</b>	Date Time	Technician Name	Statu	ıs	R	Remark	Sign	
	21-07-2025 04:27:09	Atique Salmani	Comple	eted	cabling required ground floor lift swich + plug po	er to ground floor lift d 30 metr cabling and rack reqired poe int .and camera need 6 according to leone		-
	21-07-2025 04:27:08	Atique Salmani	Comple	eted	cabling required ground floor lift swich + plug po	er to ground floor lift d 30 metr cabling and rack reqired poe int .and camera need 6 according to leone	1 / 1/10//	<i>y</i> /.
	21-07-2025 10:57:10	Atique Salmani	New				-	

Previous Complain History :	Date Time Technician Name		Remark		
	02-08-2025 12:56:26	Atique Salmani	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.		
	31-07-2025 10:33:12	Atique Salmani	In 151 nvr main gate camera 19 metr condute cabling done with		