







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15647																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9930943918																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	26-08-2025 11:33:01																						
Vendor Details :																									
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	Turf cameras need to check and 1 camera cable faulty need to change																								
Technician Comment :	22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-08-2025 01:20:56</td><td>Atique Salmani</td><td>Completed</td><td>22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr</td><td></td></tr><tr><td>26-08-2025 01:20:56</td><td>Atique Salmani</td><td>Completed</td><td>22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr</td><td></td></tr><tr><td>26-08-2025 11:33:07</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-08-2025 01:20:56	Atique Salmani	Completed	22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr		26-08-2025 01:20:56	Atique Salmani	Completed	22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr		26-08-2025 11:33:07	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-08-2025 01:20:56	Atique Salmani	Completed	22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr																						
26-08-2025 01:20:56	Atique Salmani	Completed	22 metr cabling done and one replacment camera installation done working ok one camera turf end corner female connector issue so collect it for service centr																						
26-08-2025 11:33:07	Atique Salmani	New		-																					

Previous Complain History :	Date Time	Technician Name	Remark
	10-09-2025 05:12:37	Siddhesh Chavan	Turf Camera 16 = cabling change and camera issue resolved KG out Camera 5 = new camera install ans working ok Camera 13 = camera service centre mai hai NVR 167 Camera 4 = camera no link issue camera take to office for checking and cable need to check Camera 14 = no recoding view so pending DVR 165 IP camera 1 = need to change camera bullet camera NVR 151 Camera 9 = camera offline issue resolved and gate side new poe switch install and old take to office
	06-09-2025 11:19:19	ChandanYadav	NVR 151 camara no 9 camera working ok and required the 4 port switch. Cctv working ok