Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details: VE6507										
Priority:	Low									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	9930943918									
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985						
Ticket Type :	Complain	Date & Time :	04-10-2022 02:36:46							
Vendor Details :										
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon					
Address:										
Mumbai , , , , N	Maharashtra									
AMC Details :										
Expiry Date :	31-03-2021 12:00:00		Type:	Non-Comprehensive						
Product Name :	CCTV									
Complain:	DVR beep sound issue in KG Section DVR Bus No. 6 - 2 cameras waves issue NVR 151 camera no. 13 not working NVR 157 camera no. 11 Hazy (Waves) NVR 159 camera no. 13 Alignment issue NVR 163 Camera no. 10 and 14 Hazy NVR 165 camera no. 1 and 7 Alignment issu									
Technician Comment :	Kg dvr beep sound issue resolved because one camera discount to beep sound and desable beep sound 2) Bus no 6 camera video waves issue resolved dvr side recontion 3) NVR 151 13 no camera cable issue need to change cable and ip camera working ok 4)Dvr 157 camera no 11 waves issue resolved dvr side BNC connector change 5) Dvr 159 camera no 13 angle setting done 6) Dvr 163 camera no 10 blur issue resolved because camera lens upside colour paint clean and camera video working Camera no 14 working okay and angle setting done 7) dvr 165 camera no 1,7 angle setting done and working okay									
Complain Operator :	Desktop - Apurva Vajaria									
Remark :	Kg dvr beep sound issue resolved because one camera discount to beep sound and desable beep sound 2) Bus no 6 camera video waves issue resolved dvr side recontion 3) NVR 151 13 no camera cable issue need to change cable and ip camera working ok 4)Dvr 157 camera no 11 waves issue resolved dvr side BNC connector change 5) Dvr 159 camera no 13 angle setting done 6) Dvr 163 camera no 10 blur issue resolved because camera lens upside colour paint clean and camera video working Camera no 14 working okay and angle setting done 7) dvr 165 camera no 1,7 angle setting done and working okay									

Status History :	Date Time	Technician Name	Sta	tus	Remark	Sign
	06-10-2022 03:26:36	Siddhesh Chavan	Comp	oleted	Kg dvr beep sound issue resolved because one camera discount to beep sound and desable beep sound 2) Bus no 6 camera video waves issue resolved dvr side recontion 3) NVR 151 13 no camera cable issue need to change cable and ip camera working ok 4)Dvr 157 camera no 11 waves issue resolved dvr side BNC connector change 5) Dvr 159 camera no 13 angle setting done 6) Dvr 163 camera no 10 blur issue resolved because camera lens upside colour paint clean and camera video working Camera no 14 working okay and angle setting done 7) dvr 165 camera no 1,7 angle setting done and working okay	
	04-10-2022 02:36:58	Siddhesh Chavan	New			-
	04-10-2022 02:36:46	Siddhesh Chavan	New			-
Previous Complain History :	Date Time	Technician	Name	Remark		
	23-09-2022 10:19:	28 Siddhesh Cl	havan			
	10-09-2022 11:05:	10-09-2022 11:05:18 Siddhesh Ch		Prashant visited on 17.09.2022 - Bus no. 09 - Hikvision DV brought in office Bus no. 8 - CP plus dvr remove for repair brought in office restart issued		