Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : $| \mathbf{W} :$ www.vallabhenterprises.com $\mathbf{E} :$ vallabhsecure@yahoo.co.in

Service Status Details :	VE2146							
Priority :	High							
Created By :	Customer - Madhu Sir- Mt							
Complaint Mob. No. :	9742015015							
Technician Name :				Technic :	Technician Mobile :			
Ticket Type :	Complain Date & Time :		31-10-2020 10:29:56					
Vendor Details :								
Company Name/Client Name :	Concentrix Services India Private Limited - MT	ervices India : rivate Limited -		974201	5015	Name :	Name : Madhu Sir- Mt	
Address :								
Bangalore , , , 560037 , Karnataka								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00			Type :				
Product Name :	CCTV							
Complain :	2ND Floor GHP PBA Door CCTV Camera Is Not Working ,Please Do The Needful							
Technician Comment :	:							
Complain Operator :	Desktop - Madhu Sir- Mt							
Remark :	1 bnc connector replaced. Camera working ok							
Status History :	Date Time		Technician Name		Status	Ren	nark	Sign
	03-11-2020 10:14:16				Completed			-
	31-10-2020 10:29:56		New		New			-
Previous Complain History :	Date Time Technicia		ian Name		Remark			
	14-11-2020 08:37:53			All access door problem solved. Now all doors working properly Buzzer working properly				
	10-11-2020 02:50:42		We checked the came BNC connector problem now that camera is working					