




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1164																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7738060558																								
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																					
Ticket Type :	Complain	Date & Time :	17-02-2020 03:46:08																						
Vendor Details :																									
Company Name/Client Name :	Vinayak Developers (Mahavir Spring)	Customer's Mobile :	7738060558	Name :	Maresh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	need to install 2 bullet cameras																								
Technician Comment :	1 camera rinstolesn and 1 cebl folty 4 tb hard disk paropr recording done																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1 camera rinstolesn and 1 cebl folty 4 tb hard disk paropr recording done																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-02-2020 09:51:28</td><td>Shiva Meena</td><td>Completed</td><td>1 camera rinstolesn and 1 cebl folty 4 tb hard disk paropr recording done</td><td></td></tr><tr><td>19-02-2020 10:32:51</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>17-02-2020 03:46:08</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-02-2020 09:51:28	Shiva Meena	Completed	1 camera rinstolesn and 1 cebl folty 4 tb hard disk paropr recording done		19-02-2020 10:32:51	Shiva Meena	New		-	17-02-2020 03:46:08	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																					
20-02-2020 09:51:28	Shiva Meena	Completed	1 camera rinstolesn and 1 cebl folty 4 tb hard disk paropr recording done																						
19-02-2020 10:32:51	Shiva Meena	New		-																					
17-02-2020 03:46:08	Shiva Meena	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-06-2023 11:07:21</td><td>Atique Salmani</td><td>Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .</td></tr><tr><td>20-05-2023 11:21:08</td><td>YogeshDesai</td><td>Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-06-2023 11:07:21	Atique Salmani	Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .	20-05-2023 11:21:08	YogeshDesai	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx											
Date Time	Technician Name	Remark																							
19-06-2023 11:07:21	Atique Salmani	Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .																							
20-05-2023 11:21:08	YogeshDesai	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx																							