Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE2366						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	7738060558						
Technician Name :	Atique Salmani		Technician	Mobile	8080922984		
Ticket Type:	Complain	Date & Time:	05-12-2020	0 10:07:37			
Vendor Details :			•				
Company Name/Client Name :	Vinayak Developers (Mahavir Spring)	Customer's Mobile :	773806055	8	Name :	Malesh Sir	
Address:					-		
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:				
Product Name :	CCTV						
Complain:	some cameras issue need to do survey for 2 new cameras						
Technician Comment :	installed 2 cameras and Angel set working ok.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	installed 2 cameras and Angel set working ok.						
Status History :	Date Time	Technician Name	Status		Remark	Sign	
	24-12-2020 02:16:59	Atique Salmani	Completed		cameras and working ok.		
	24-12-2020 09:54:46	Atique Salmani	New			-	
	22-12-2020 10:24:03	Atique Salmani	New			-	
	10-12-2020 06:05:00	Atique Salmani	New			-	
	05-12-2020 06:18:10	Atique Salmani	Work Pending	New rcc w camera ar damege a	mera not working work not checking and 1 camera cable and new Camera 00 mtr above		
	05-12-2020 06:10:33	Atique Salmani	New			-	
	05-12-2020 10:08:04	Atique Salmani	New			<u> </u>	
	05-12-2020 10:07:38	Atique Salmani	New			-	

Previous Complain History :	Date Time	Technician Name	Remark		
	19-06-2023 11:07:21	Atique Salmani	Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .		
	20-05-2023 11:21:08	YogeshDesai	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx		