Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Do	etails : VE2877						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	7738060558						
Technician Name :	Rishi Desai		Technici	ian Mobile	8369234074		
Ticket Type :	Complain Date & Time:		22-03-20	021 09:56:35			
Vendor Details :							
Company Name/Client Name:	Vinayak Developers (Mahavir Spring)	Customer's Mobile :	7738060)558	Name :	Malesh Sir	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:				
Product Name :	CCTV						
Complain :	set PTZ on auto moving meet harshil sir						
Technician Comment :	One Ptz camera auto mode preset done. 2 cameras Not working, One Camera Needed Bnc pin to change because of rcc, One camera no connection ot bnc and dc and one camera angle setting.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark :	One Ptz camera auto mode preset done. 2 cameras Not working , One Camera Needed Bnc pin t change because of rcc, One camera no connection ot bnc and dc and one camera angle setting.						
Status History :	Date Time	Technician Name	Status	F	Remark	Sign	
	22-03-2021 03:39:40	RishiDesai	Completed	preset done. working, One Bnc pin to charce, One came	era auto mode 2 cameras Not e Camera Needed ange because of era no connection and one camera	Smlymati	
	22-03-2021 09:57:17	RishiDesai	New			-	
	22-03-2021 09:56:35	RishiDesai	New			-	

Previous Complain History :	Date Time	Technician Name	Remark	
	19-06-2023 11:07:21	Atique Salmani	Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .	
	20-05-2023 11:21:08	YogeshDesai	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable 150 to 200 mtrs approx	