Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE8613 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 7738060558 Mob. No. : **Technician** Atique Salmani **Technician Mobile** 8080922984 Name : New Installation Date & Time : 19-06-2023 11:07:21 **Ticket Type : Vendor Details :** 7738060558 Vinayak Customer's Mobile Malesh Sir Company Name : Name/Client Developers (Mahavir Spring) Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain** : 1)Gate no 2 camera cable break Need to do cabling 2)one new bullet camera need to install 3)Ptz camera need to be shift from sale office to side building Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also **Technician** done set preset now total 7 cameras working ok . **Comment**: Complain Desktop - Apurva Vajaria **Operator** : Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also **Remark** : done set preset now total 7 cameras working ok . **Status History : Date Time Technician Name** Status Remark Sign 22-06-2023 06:11:43 Atique Salmani Completed Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok . 22-06-2023 10:12:30 Atique Salmani New 21-06-2023 10:06:41 Atique Salmani New _ 19-06-2023 11:07:36 Atique Salmani New

Previous Complain History :	Date Time	Technician Name	Remark
	20-05-2023 11:21:08	YogeshDesai	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx
	02-05-2023 11:52:40	PravinJagade	1 camera not working resolve working done 2 camera angle setting done. 1 camera new BNC change.