




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE998</b>																									
<b>Priority :</b>	High																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	7738060558																								
<b>Technician Name :</b>	Shiva Meena		<b>Technician Mobile :</b>	7489567735																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	28-01-2020 12:42:35																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Vinayak Developers (Mahavir Spring)	<b>Customer's Mobile :</b>	7738060558	<b>Name :</b>	Malesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	need to install bullet cameras																								
<b>Technician Comment :</b>	3 camera angel setting 3 camera ristolessn done																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	3 camera angel setting 3 camera ristolessn done																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-01-2020 04:39:38</td><td>Shiva Meena</td><td>Completed</td><td>3 camera angel setting 3 camera ristolessn done</td><td></td></tr><tr><td>28-01-2020 12:42:44</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>28-01-2020 12:42:36</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-01-2020 04:39:38	Shiva Meena	Completed	3 camera angel setting 3 camera ristolessn done		28-01-2020 12:42:44	Shiva Meena	New		-	28-01-2020 12:42:36	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																					
29-01-2020 04:39:38	Shiva Meena	Completed	3 camera angel setting 3 camera ristolessn done																						
28-01-2020 12:42:44	Shiva Meena	New		-																					
28-01-2020 12:42:36	Shiva Meena	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-06-2023 11:07:21</td><td>Atique Salmani</td><td>Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .</td></tr><tr><td>20-05-2023 11:21:08</td><td>YogeshDesai</td><td>Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-06-2023 11:07:21	Atique Salmani	Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .	20-05-2023 11:21:08	YogeshDesai	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx											
Date Time	Technician Name	Remark																							
19-06-2023 11:07:21	Atique Salmani	Gate no.3 reconnection issue resolved and gate nmr 2 angel set ptz reinstalled and shifting also done set preset now total 7 cameras working ok .																							
20-05-2023 11:21:08	YogeshDesai	Two camera angle setting done One camera on gate no 3 camera reconnected camera working ok One camera inside near gate no 3 one camera was disconnected cable was lying on ground we reconnected and camera is working ok. Camera view showing black and white need to change lense need to be cleaned. Gate no 2 camera cable break from two sides need to change cable and one new bullet camera also required.camera cable about 300 to 400 mtrs approx. Ptz camera need to be shifted from sale office to side building approx cable150 to 200 mtrs approx																							