




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11472																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930235307																			
Technician Name :	Anil Yadav		Technician Mobile :	8090436743																
Ticket Type :	Complain	Date & Time :	25-04-2024 11:01:57																	
Vendor Details :																				
Company Name/Client Name :	Apex Creators - Dhruv Zaveri	Customer's Mobile :	9930235307	Name :	Manor															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	intrusion																			
Complain :	instrusion panel need to install material at site																			
Technician Comment :	Intrusion panel installed.But power not is there. I do check temporary power system is properly working.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Intrusion panel installed.But power not is there. I do check temporary power system is properly working.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-04-2024 12:09:15</td><td>Anil Yadav</td><td>Completed</td><td>Intrusion panel installed.But power not is there. I do check temporary power system is properly working.</td><td></td></tr><tr><td>26-04-2024 12:03:02</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-04-2024 12:09:15	Anil Yadav	Completed	Intrusion panel installed.But power not is there. I do check temporary power system is properly working.		26-04-2024 12:03:02	Anil Yadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-04-2024 12:09:15	Anil Yadav	Completed	Intrusion panel installed.But power not is there. I do check temporary power system is properly working.																	
26-04-2024 12:03:02	Anil Yadav	New		-																

Previous Complain History :	Date Time	Technician Name	Remark
	18-11-2023 10:51:13	Ravi Rajbhar	Zaveri wildernets Villa no. 15 - Boundary side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 18 Boundary viewing camera side camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 16 - road side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 17 Electric generator side viewing camera connector cut full off (need to change camera) Play ground Boundary side viewing camera cable breck two pair camera ok and swape to Electric generator place Villa no. 21 Boundary camera cable faulty camera our side checking pending Club house upper side camera cable faulty Club house kitchen in side Camera cable faulty Club house in side dining table viewing camera cable faulty Club house Garden viewing camera cable cut but our side cable jointor uesd then ok working but need to change cable Villa no. 12 Road side camera viewing camera broken (faulty) cable ok Villa no. 12 Boundary side viewing Camera faulty Cable ok Villa no. 10 Boundary side viewing Camera connector faulty Cable check one pair cable breck orange white Villa no.10 Road side viewing camera cable not found Security cabin main gate out side camera connector issue cable ok Or main gate in side Camera cable breck (camera not check our side) Villa no. 2 Boundary side camera viewing Cable ok Camera connector faulty And club house kitchen or dining table cable faulty And camera missing one And club house above camera cable joint and ok working done temporary infrom to Deepak sir Main gate feber cable disconnect need to change feber cable and media convetor Total 22 camera ok working villa no. 07 need to install intusion panal with panic switch
	10-03-2023 10:30:46	Ravi Rajbhar	Zaveri wildernets Villa no. 15 - Boundary side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 18 Boundary viewing camera side camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 16 - road side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 17 Electric generator side viewing camera connector cut full off (need to change camera) Play ground Boundary side viewing camera cable breck two pair camera ok and swape to Electric generator place Villa no. 21 Boundary camera cable faulty camera our side checking pending Club house upper side camera cable faulty Club house kitchen in side Camera cable faulty Club house in side dining table viewing camera cable faulty Club house Garden viewing camera cable cut but our side cable jointor uesd then ok working but need to change cable Villa no. 12 Road side camera viewing camera broken (faulty) cable ok Villa no. 12 Boundary side viewing Camera faulty Cable ok Villa no. 10 Boundary side viewing Camera connector faulty Cable check one pair cable breck orange white Villa no.10 Road side viewing camera cable not found Security cabin main gate out side camera connector issue cable ok Or main gate in side Camera cable breck (camera not check our side) Villa no. 2 Boundary side camera viewing Cable ok Camera connector faulty