Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : $| \mathbf{W} :$ www.vallabhenterprises.com $\mathbf{E} :$ vallabhsecure@yahoo.co.in

Service Status Details : VE1362								
Priority :	High							
Created By :	Admin - Apurva Vajaria							
Complaint Mob. No. :	9930235307							
Technician Name :	Sachin Pawar		Technician Mobile :	808092	8080922981			
Ticket Type :	Complain Date & Time :		12-03-2020 03:10:3	:31				
Vendor Details :			•					
Company Name/Client Name :	Apex Creators - Dhruv Zaveri	Customer's Mobile :	9930235307	Name :	Man	Manor		
Address :								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00		Type :					
Product Name :	CCTV							
Complain :	need to complete all work at site and to give handover							
Technician Comment :								
Complain Operator :	Desktop - Apurva Vajaria							
Remark :								
Status History :	Date Time		echnician Name	Status	Remark	Sign		
	13-03-2020 05:40:28 SachinI		Pawar	New		-		
	12-03-2020 03:10:31 Sa		Pawar	New		-		

Previous Complain History :	Date Time	Technician Name	Remark		
	10-03-2023 10:30:46	Ravi Rajbhar	Zaveri wildernets Villa no. 15 - Boundary side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 18 Boundary viewing camera side camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 16 - road side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 17 Electric generator side viewing camera connector cut full off (need to change camera) Play ground Boundary side viewing camera cable breck two pair camera ok and swape to Electric generator place Villa no. 21 Boundary camera cable faulty camera our side checking pending Club house upper side camera cable faulty Club house kitchen in side Camera cable faulty Club house in side dining table viewing camera cable faulty Club house Garden viewing camera cable cut but our side cable jointor uesd then ok working but need to change cable Villa no. 12 Road side camera viewing camera broken (faulty) cable ok Villa no. 12 Boundary side viewing Camera faulty Cable ok Villa no. 10 Boundary side viewing Camera connector faulty Cable ok Villa no. 10 Boundary side viewing Camera connector faulty Cable ok Villa no. 20 Road side camera connector faulty Cable check one pair cable breck orange white Villa no.10 Road side viewing camera cable not found Security cabin main gate out side camera not check our side) Villa no. 2 Boundary side camera viewing Cable ok Camera connector faulty		
	26-04-2022 03:47:58	Ravi Rajbhar	banglow no. 15 and banglow no. 17 out door camera with screen install and ok working done one to one only and one camera repair return with install but cable inssu inform to Deepak sir		