

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3548																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930235307																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	03-08-2021 09:59:36																	
Vendor Details :																				
Company Name/Client Name :	Apex Creators - Dhruv Zaveri	Customer's Mobile :	9930235307	Name :	Manor															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	VDP																			
Complain :	VDP & Intercom issue																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :																				
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-08-2021 09:59:53</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>03-08-2021 09:59:36</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-08-2021 09:59:53	Ravi Rajbhar	New		-	03-08-2021 09:59:36	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-08-2021 09:59:53	Ravi Rajbhar	New		-																
03-08-2021 09:59:36	Ravi Rajbhar	New		-																

Previous Complain History :	Date Time	Technician Name	Remark
	10-03-2023 10:30:46	Ravi Rajbhar	Zaveri wildernets Villa no. 15 - Boundary side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 18 Boundary viewing camera side camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 16 - road side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 17 Electric generator side viewing camera connector cut full off (need to change camera) Play ground Boundary side viewing camera cable breck two pair camera ok and swape to Electric generator place Villa no. 21 Boundary camera cable faulty camera our side checking pending Club house upper side camera cable faulty Club house kitchen in side Camera cable faulty Club house in side dining table viewing camera cable faulty Club house Garden viewing camera cable cut but our side cable jointor uesd then ok working but need to change cable Villa no. 12 Road side camera viewing camera broken (faulty) cable ok Villa no. 12 Boundary side viewing Camera faulty Cable ok Villa no. 10 Boundary side viewing Camera connector faulty Cable check one pair cable breck orange white Villa no.10 Road side viewing camera cable not found Security cabin main gate out side camera connector issue cable ok Or main gate in side Camera cable breck (camera not check our side) Villa no. 2 Boundary side camera viewing Cable ok Camera connector faulty
	26-04-2022 03:47:58	Ravi Rajbhar	banglow no. 15 and banglow no. 17 out door camera with screen install and ok working done one to one only and one camera repair return with install but cable inssu inform to Deepak sir