Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status	Details : VE7823							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9930235307							
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965				
Ticket Type :	Complain	Date & Time :	10-03-2023 10:30:46					
Vendor Details	s :							
Company Name/Client Name:	Apex Creators - Dhruv Zaveri	Customer's Mobile :	9930235307	Name :	Manor			
Address:								
Mumbai , , , ,	Maharashtra							
AMC Details :				_				
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name :	CCTV							
Complain:	some camera off issue							
Technician Comment :	Zaveri wildernets Villa no. 15 - Boundary side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 18 Boundary viewing camera side camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 16 - road side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 17 Electric generator side viewing camera connector cut full off (need to change camera) Play ground Boundary side viewing camera cable breck two pair camera ok and swape to Electric generator place Villa no. 21 Boundary camera cable faulty camera our side checking pending Club house upper side camera cable faulty Club house kitchen in side Camera cable faulty Club house in side dining table viewing camera cable faulty Club house Garden viewing camera cable cut but our side cable jointor uesd then ok working but need to change cable Villa no. 12 Road side camera viewing camera broken (faulty) cable ok Villa no. 12 Boundary side viewing Camera faulty Cable ok Villa no. 10 Boundary side viewing camera connector faulty Cable check one pair cable breck orange white Villa no.10 Road side viewing camera cable not found Security cabin main gate out side camera connector issue cable ok Or main gate in side Camera cable breck (camera not check our side) Villa no. 2 Boundary side camera viewing Cable ok Camera connector faulty							
Complain Operator :	Desktop - Apurva Vajaria							

Remark:

Complain History :

26-04-2022 03:47:58

03-08-2021 09:59:36

Ravi Rajbhar

Ravi Rajbhar

Zaveri wildernets Villa no. 15 - Boundary side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 18 Boundary viewing camera side camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 16 - road side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 17 Electric generator side viewing camera connector cut full off (need to change camera) Play ground Boundary side viewing camera cable breck two pair camera ok and swape to Electric generator place Villa no. 21 Boundary camera cable faulty camera our side checking pending Club house upper side camera cable faulty Club house kitchen in side Camera cable faulty Club house in side dining table viewing camera cable faulty Club house Garden viewing camera cable cut but our side cable jointor uesd then ok working but need to change cable Villa no. 12 Road side camera viewing camera broken (faulty) cable ok Villa no. 12 Boundary side viewing Camera faulty Cable ok Villa no. 10 Boundary side viewing Camera connector faulty Cable check one pair cable breck orange white Villa no.10 Road side viewing camera cable not found Security cabin main gate out side camera connector issue cable ok Or main gate in side Camera cable breck (camera not check our side) Villa no. 2 Boundary side camera viewing Cable ok Camera connector faulty

Status History:	Date Time	Technician Name	Status	Remark	Sign
	15-03-2023 11:02:36	Ravi Rajbhar	Completed	Zaveri wildernets Villa no. 15 - Boundary side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 18 Boundary viewing camera side camera connector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 16 - road side camera viewing camera connector cut our side joint cable then ok working but temporary going on (need to change camera onnector cut our side joint cable then ok working but temporary going on (need to change camera) Villa no. 17 Electric generator side viewing camera connector cut full off (need to change camera) Play ground Boundary side viewing camera cable breck two pair camera ok and swape to Electric generator place Villa no. 21 Boundary camera cable faulty camera our side checking pending Club house upper side camera cable faulty Club house kitchen in side Camera cable faulty Club house in side dining table viewing camera cable cut but our side cable jointor uesd then ok working but need to change cable Villa no. 12 Road side camera viewing camera broken (faulty) cable ok Villa no. 12 Boundary side viewing Camera faulty Cable ok Villa no. 10 Boundary side viewing Camera connector faulty Cable check one pair cable breck orange white Villa no.10 Road side viewing camera cable not found Security cabin main gate out side camera connector issue cable ok Or main gate in side Camera cable breck (camera not check our side) Villa no. 2 Boundary side camera viewing Cable ok Camera connector faulty	Prince
	15-03-2023 10:31:56	Ravi Rajbhar	New		-
	14-03-2023 10:28:01	Ravi Rajbhar	New		-
	10-03-2023 10:30:56	Ravi Rajbhar	New		-

banglow no. 15 and banglow no. 17 out door camera with screen install and ok working done one to one only and one camera repair

return with install but cable inssu inform to Deepak sir