


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1942					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9869695781				
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985	
Ticket Type :	Complain	Date & Time :	01-10-2020 06:23:31		
Vendor Details :					
Company Name/Client Name :	Kuber Co Op Scoiety	Customer's Mobile :	9869695781	Name :	Mansukh Sir
Address :					
Mumbai , , , 400067 , Maharashtra					
AMC Details :					
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive	
Product Name :	Intercom				
Complain :	lift intercom issue				
Technician Comment :	A/703 old cable is dead so not working. I do connect spar cable now line ok but rojor box and phone need. A/ 303 Phone and rojor need. B/ 702 cable not find inside flat. flat outside line is OK. B/ 703 only phone change. B/ 502 rojor box and phone of cable need. B/ 402 line not working because system to B wing krone cables is dead. cable need to change after issue will be resolve.				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	A/703 old cable is dead so not working. I do connect spar cable now line ok but rojor box and phone need. A/ 303 Phone and rojor need. B/ 702 cable not find inside flat. flat outside line is OK. B/ 703 only phone change. B/ 502 rojor box and phone of cable need. B/ 402 line not working because system to B wing krone cables is dead. cable need to change after issue will be resolve.				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	24-10-2020 10:40:14	Siddhesh Chavan	Completed		-
	22-10-2020 10:56:42	Siddhesh Chavan	New		-
	19-10-2020 05:59:21	Siddhesh Chavan	New		-
	19-10-2020 10:38:44	Siddhesh Chavan	New		-
	05-10-2020 06:24:41	Siddhesh Chavan	Client Side	A/703 old cable is dead so not working. I do connect spar cable now line ok but rojor box and phone need. A/ 303 Phone and rojor need. B/ 702 cable not find inside flat. flat outside line is OK. B/ 703 only phone change. B/ 502 rojor box and phone of cable need. B/ 402 line not working because system to B wing krone cables is dead. cable need to change after issue will be resolve.	
	05-10-2020 11:09:29	Siddhesh Chavan	New		-
	01-10-2020 06:23:32	Siddhesh Chavan	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	07-08-2023 10:59:39	ChandanYadav	Suresh Bhai unko camera ka recording dikhana tha 8 Jun par dvr me 28 Jun se recording hai jiske wajah se recording nahi mil paya.		
	31-07-2023 10:45:59	MayurYadav	Recording check and showing to client		