




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2083</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9869695781																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	22-10-2020 06:26:27																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Kuber Co Op Scoiety	Customer's Mobile :	9869695781	Name :	Mansukh Sir																				
<b>Address :</b>																									
Mumbai , , , 400067 , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	Ppm																								
<b>Complain :</b>	cctv																								
<b>Technician Comment :</b>	cctv ppm done and 2 nd dvr hdd issue one camera video issue and camera checking for a office and all camera clining and working ok																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	cctv ppm done and 2 nd dvr hdd issue one camera video issue and camera checking for a office and all camera clining and working ok																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-10-2020 09:39:20</td><td>Siddhesh Chavan</td><td>Completed</td><td>cctv ppm done and 2 nd dvr hdd issue one camera video issue and camera checking for a office and all camera clining and working ok</td><td></td></tr><tr><td>22-10-2020 06:26:45</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>22-10-2020 06:26:27</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-10-2020 09:39:20	Siddhesh Chavan	Completed	cctv ppm done and 2 nd dvr hdd issue one camera video issue and camera checking for a office and all camera clining and working ok		22-10-2020 06:26:45	Siddhesh Chavan	New		-	22-10-2020 06:26:27	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-10-2020 09:39:20	Siddhesh Chavan	Completed	cctv ppm done and 2 nd dvr hdd issue one camera video issue and camera checking for a office and all camera clining and working ok																						
22-10-2020 06:26:45	Siddhesh Chavan	New		-																					
22-10-2020 06:26:27	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-10-2020 10:41:01</td><td>YogeshDesai</td><td>DVR of 16 ch repaired and returned DVR reinstall ed all cameras are working and can be viewed in tv</td></tr><tr><td>01-10-2020 06:23:31</td><td>Siddhesh Chavan</td><td>A/703 old cable is dead so not working. I do connect spar cable now line ok but rojor box and phone need. A/ 303 Phone and rojor need. B/ 702 cable not find inside flat. flat outside line is OK. B/ 703 only phone change. B/ 502 rojor box and phone of cable need. B/ 402 line not working because system to B wing krone cables is dead. cable need to change after issue will be resolve.</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-10-2020 10:41:01	YogeshDesai	DVR of 16 ch repaired and returned DVR reinstall ed all cameras are working and can be viewed in tv	01-10-2020 06:23:31	Siddhesh Chavan	A/703 old cable is dead so not working. I do connect spar cable now line ok but rojor box and phone need. A/ 303 Phone and rojor need. B/ 702 cable not find inside flat. flat outside line is OK. B/ 703 only phone change. B/ 502 rojor box and phone of cable need. B/ 402 line not working because system to B wing krone cables is dead. cable need to change after issue will be resolve.											
Date Time	Technician Name	Remark																							
24-10-2020 10:41:01	YogeshDesai	DVR of 16 ch repaired and returned DVR reinstall ed all cameras are working and can be viewed in tv																							
01-10-2020 06:23:31	Siddhesh Chavan	A/703 old cable is dead so not working. I do connect spar cable now line ok but rojor box and phone need. A/ 303 Phone and rojor need. B/ 702 cable not find inside flat. flat outside line is OK. B/ 703 only phone change. B/ 502 rojor box and phone of cable need. B/ 402 line not working because system to B wing krone cables is dead. cable need to change after issue will be resolve.																							