Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Deta	ails: VE6280							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9869695781							
Technician Name	Atique Salmani		Technician :	Mobile 8080922984				
Ticket Type :	Complain	Date & Time :	30-08-2022 06:39:54					
Vendor Details :	•							
Company Name/Client Name :	Kuber Co Op Scoiety	Customer's Mobile :	9869695781 Name:		Mansukh Sir			
Address:					-			
Mumbai , , , 40006	7 , Maharashtra							
AMC Details:								
Expiry Date :	31-03-2021 12:00:	Type:	Non-Compre		hensive			
Product Name:	CCTV							
Complain:	main gate camera angle need to set							
Technician Comment :	one camera main gate angel set but it's fixed on ply so ply has rushted need new fabrication bracket for boath camera told to mansukh sir							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	one camera main gate angel set but it's fixed on ply so ply has rushted need new fabrication bracket for boath camera told to mansukh sir							
Status History:	Date Time	Technician Name	Status		Remark		Sign	
	31-08-2022 11:03:54	4 Atique Salmani	Completed	one camera main gate angel set but it's fixed on ply so ply has rushted need new fabrication bracket for boath camera told to mansukh sir		July 1		
	30-08-2022 06:40:09	Atique Salmani	New			-		
	30-08-2022 06:39:54	1 Atique Salmani	New				-	
Previous Complain History	Date Time	Technician Name		Remark				
	29-08-2022 11:48:00	Sonu Kumar	recording see	ording seen completed				
	27-08-2022 09:59:03	3 Atique Salmani	a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .					