Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3729 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9930908642 **No. :** Technician Neeraj Chauhan **Technician Mobile** 8898885764 Name : Complain 30-08-2021 11:44:08 **Ticket Type :** Date & Time : **Vendor Details :** Flemingo Duty Customer's Mobile 9930908642 Company Name : Methue Name/Client Free Shop Pvt Name : Ltd Address : Mumbai,,,, Maharashtra **AMC Details :** 30-07-2021 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** Ppm **Complain**: CCTV all camera cleaning and housing cleaning and dvr time date set and and dvr function check and Technician 1 camera no video issue solve and 1 camera not working and 16 channel dvr not working and **Comment** : ppm done Complain Desktop - Apurva Vajaria **Operator** : all camera cleaning and housing cleaning and dvr time date set and and dvr function check and **Remark** : 1 camera no video issue solve and 1 camera not working and 16 channel dvr not working and ppm done **Status History : Date Time Technician Name Status** Remark Sign 30-08-2021 Neeraj Chauhan Work all camera cleaning and 05:07:30 Pending housing cleaning and dvr time date set and and dvr function check and 1 camera no video issue solve and 1 camera not working and 16 channel dvr not working and ppm done 30-08-2021 Neeraj Chauhan New 11:44:23 30-08-2021 Neeraj Chauhan New 11:44:08

Previous Complain History :	Date Time	Technician Name	Remark
	04-02-2022 10:30:03	Siddhesh Chavan	ppm done and dack side gate camera rj6 cable issue and camera working ok and camera take to dvr room and 1 st no camera recording just started
	04-06-2021 10:18:10	YogeshDesai	ppm work completed all cameras working indvr no 2 one camera issue indvr no 1 camera issue not working one camera issue sloved one dvr adapter changed in dvr no2 adapter was faulty new power supply installed dvr working ok and on recording