




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14023																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9167835007																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	06-02-2025 01:24:11																	
Vendor Details :																				
Company Name/Client Name :	Kesari Tours Pvt Ltd	Customer's Mobile :	9167835007	Name :	Milind Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Access																			
Complain :	Bolt lock issue need to check																			
Technician Comment :	There is two smps allready used 1st in server and 2nd reception so reception smps was weak so changed self smps working ok.on under observation.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	There is two smps allready used 1st in server and 2nd reception so reception smps was weak so changed self smps working ok.on under observation.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-02-2025 05:12:57</td><td>Atique Salmani</td><td>Completed</td><td>There is two smps allready used 1st in server and 2nd reception so reception smps was weak so changed self smps working ok.on under observation.</td><td></td></tr><tr><td>06-02-2025 01:24:26</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-02-2025 05:12:57	Atique Salmani	Completed	There is two smps allready used 1st in server and 2nd reception so reception smps was weak so changed self smps working ok.on under observation.		06-02-2025 01:24:26	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
06-02-2025 05:12:57	Atique Salmani	Completed	There is two smps allready used 1st in server and 2nd reception so reception smps was weak so changed self smps working ok.on under observation.																	
06-02-2025 01:24:26	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead></table>					Date Time	Technician Name	Remark												
Date Time	Technician Name	Remark																		