

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10273																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9004047839																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	14-12-2023 02:18:16																	
Vendor Details :																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	boundary 2 camera not working																			
Technician Comment :	2 bondery camera no link issue resoved and all camera working oo																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	2 bondery camera no link issue resoved and all camera working oo																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-12-2023 11:16:30</td><td>Siddhesh Chavan</td><td>Completed</td><td>2 bondery camera no link issue resoved and all camera working oo</td><td></td></tr><tr><td>15-12-2023 10:31:23</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-12-2023 11:16:30	Siddhesh Chavan	Completed	2 bondery camera no link issue resoved and all camera working oo		15-12-2023 10:31:23	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
15-12-2023 11:16:30	Siddhesh Chavan	Completed	2 bondery camera no link issue resoved and all camera working oo																	
15-12-2023 10:31:23	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-12-2023 04:26:58</td><td>Atique Salmani</td><td>One boundry camera was off harden side so reconnection from camera end working ok and this camera is working on only 6 pair .</td></tr><tr><td>09-12-2023 11:46:30</td><td>MayurYadav</td><td>One boundary camera issue solve</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-12-2023 04:26:58	Atique Salmani	One boundry camera was off harden side so reconnection from camera end working ok and this camera is working on only 6 pair .	09-12-2023 11:46:30	MayurYadav	One boundary camera issue solve						
Date Time	Technician Name	Remark																		
19-12-2023 04:26:58	Atique Salmani	One boundry camera was off harden side so reconnection from camera end working ok and this camera is working on only 6 pair .																		
09-12-2023 11:46:30	MayurYadav	One boundary camera issue solve																		