







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14879																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9004047839																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	31-05-2025 11:42:17																											
Vendor Details :																														
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																										
Product Name :	CCTV																													
Complain :	switcher install and 1 camera need to check																													
Technician Comment :	Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-06-2025 03:35:20</td><td>Atique Salmani</td><td>Completed</td><td>Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl</td><td></td></tr><tr><td>02-06-2025 11:56:34</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>31-05-2025 05:53:48</td><td>Atique Salmani</td><td>Work Pending</td><td>switcher install and splitter problem chek the office.loby and manager cabin tv viewing not working. one camera p1 ground side camera not working.camera inside water and connecter problem.</td><td></td></tr><tr><td>31-05-2025 11:42:30</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-06-2025 03:35:20	Atique Salmani	Completed	Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl		02-06-2025 11:56:34	Atique Salmani	New		-	31-05-2025 05:53:48	Atique Salmani	Work Pending	switcher install and splitter problem chek the office.loby and manager cabin tv viewing not working. one camera p1 ground side camera not working.camera inside water and connecter problem.		31-05-2025 11:42:30	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
02-06-2025 03:35:20	Atique Salmani	Completed	Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl																											
02-06-2025 11:56:34	Atique Salmani	New		-																										
31-05-2025 05:53:48	Atique Salmani	Work Pending	switcher install and splitter problem chek the office.loby and manager cabin tv viewing not working. one camera p1 ground side camera not working.camera inside water and connecter problem.																											
31-05-2025 11:42:30	Atique Salmani	New		-																										

Previous Complain History :			
	Date Time	Technician Name	Remark
	12-06-2025 12:11:22	Ravi Rajbhar	1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve
	09-06-2025 03:24:31	Ravi Rajbhar	Two Boundary camera issue resolved and one p2 cmaera issue resolved and repair spiter install and remove new standby by