




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14950																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9004047839																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	09-06-2025 03:24:31																	
Vendor Details :																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	4 boundary cameras off issue and 1 repaired splitter need to install																			
Technician Comment :	Two Boundary camera issue resolved and one p2 cmaera issue resolved and repair spiter install and remove new standby by																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Two Boundary camera issue resolved and one p2 cmaera issue resolved and repair spiter install and remove new standby by																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-06-2025 03:28:06</td><td>Ravi Rajbhar</td><td>Completed</td><td>Two Boundary camera issue resolved and one p2 cmaera issue resolved and repair spiter install and remove new standby by</td><td></td></tr><tr><td>09-06-2025 03:24:38</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-06-2025 03:28:06	Ravi Rajbhar	Completed	Two Boundary camera issue resolved and one p2 cmaera issue resolved and repair spiter install and remove new standby by		09-06-2025 03:24:38	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
09-06-2025 03:28:06	Ravi Rajbhar	Completed	Two Boundary camera issue resolved and one p2 cmaera issue resolved and repair spiter install and remove new standby by																	
09-06-2025 03:24:38	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-06-2025 12:11:22</td><td>Ravi Rajbhar</td><td>1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve</td></tr><tr><td>31-05-2025 11:42:17</td><td>Atique Salmani</td><td>Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-06-2025 12:11:22	Ravi Rajbhar	1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve	31-05-2025 11:42:17	Atique Salmani	Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl						
Date Time	Technician Name	Remark																		
12-06-2025 12:11:22	Ravi Rajbhar	1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve																		
31-05-2025 11:42:17	Atique Salmani	Garden side 1 bullet camera issue so collect camera and installed 1.4 splitter working ok mishra ji tv view ok 2 nvr onl																		