




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE14986</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9004047839																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	12-06-2025 12:11:22																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Anmol Prestige HSG	<b>Customer's Mobile :</b>	9004047839	<b>Name :</b>	Mishra															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	21-07-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	1)1 boundary camera off issue 2)1 bms room camera off issue																			
<b>Technician Comment :</b>	1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-06-2025 04:49:05</td><td>Ravi Rajbhar</td><td>Completed</td><td>1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve</td><td></td></tr><tr><td>12-06-2025 12:11:28</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-06-2025 04:49:05	Ravi Rajbhar	Completed	1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve		12-06-2025 12:11:28	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
12-06-2025 04:49:05	Ravi Rajbhar	Completed	1 . BMS Room one cmaera issue resolved 2 . Boundary one camera issue resolved All cmaera no link issue resolve																	
12-06-2025 12:11:28	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-06-2025 10:41:19</td><td>Atique Salmani</td><td>2 camera garden side installed working ok both camera password changed by service center so now password is 123456only</td></tr><tr><td>16-06-2025 11:02:03</td><td>Ravi Rajbhar</td><td>P2 one cmaera issue resolved and ok working but cmaera connector need to change next bcz connector weak</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-06-2025 10:41:19	Atique Salmani	2 camera garden side installed working ok both camera password changed by service center so now password is 123456only	16-06-2025 11:02:03	Ravi Rajbhar	P2 one cmaera issue resolved and ok working but cmaera connector need to change next bcz connector weak						
Date Time	Technician Name	Remark																		
25-06-2025 10:41:19	Atique Salmani	2 camera garden side installed working ok both camera password changed by service center so now password is 123456only																		
16-06-2025 11:02:03	Ravi Rajbhar	P2 one cmaera issue resolved and ok working but cmaera connector need to change next bcz connector weak																		