




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2521																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9004047839																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	04-01-2021 11:17:14																											
Vendor Details :																														
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																										
Product Name :	CCTV																													
Complain :	Install 1 camera																													
Technician Comment :	one camera conection done and bnc filled up boathe end and one turf area camera Angel set and working ok . and also out side camera was hanging fixed it and working ok.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	one camera conection done and bnc filled up boathe end and one turf area camera Angel set and working ok . and also out side camera was hanging fixed it and working ok.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-01-2021 12:04:27</td><td>Atique Salmani</td><td>Completed</td><td>one camera conection done and bnc filled up boathe end and one turf area camera Angel set and working ok . and also out side camera was hanging fixed it and working ok.</td><td></td></tr><tr><td>05-01-2021 09:53:37</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>04-01-2021 11:17:33</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>04-01-2021 11:17:15</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-01-2021 12:04:27	Atique Salmani	Completed	one camera conection done and bnc filled up boathe end and one turf area camera Angel set and working ok . and also out side camera was hanging fixed it and working ok.		05-01-2021 09:53:37	Atique Salmani	New		-	04-01-2021 11:17:33	Atique Salmani	New		-	04-01-2021 11:17:15	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
05-01-2021 12:04:27	Atique Salmani	Completed	one camera conection done and bnc filled up boathe end and one turf area camera Angel set and working ok . and also out side camera was hanging fixed it and working ok.																											
05-01-2021 09:53:37	Atique Salmani	New		-																										
04-01-2021 11:17:33	Atique Salmani	New		-																										
04-01-2021 11:17:15	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 10:23:20</td><td>Atique Salmani</td><td>Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .</td></tr><tr><td>05-08-2023 02:08:47</td><td>Ravi Rajbhar</td><td>boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .	05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved																
Date Time	Technician Name	Remark																												
08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .																												
05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved																												